DISTRICT TOWN ROUTE DRAFT Route Log and Progress Chart Please Note: Errors and Omissions May Exist. WEATHERSFIELD, WINDSOR, I-91 Contact the VTrans Mapping Section with questions or concerns. **SPRINGFIELD** Base Map WEATHERSFIELD SPRINGFIELD z >WINDSOR 1 in = 2,000 feetStick Diagram STRUCTURE DESCRIPTIONS Town Center Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, Bridge <mark>29-3</mark>: Culvert - 1965 Bridge 31: ++++++ Railroad Crossings Structure No. 30009129-314201 Structure No. 2014200D3114201 Primary Structures Structure Type: Unknown Length: 9' Under Clearance: 10.0' Inspection Date: 12/2019 Secondary Structures Weight Limit: 0 Divided State Highway Facility Carried: I91 Structure Type: CGMPP ALUM SLEEVE Unknown State Highway \$ 29-7N Structure No. 2014230D3214231 Features Intersected: BROOK Divided Town Highway Inspection Date: 11/2019 Structure Type: Unknown ——— Town Highway Inspection Date: 12/2019 Maintenance: State Streams (Hydraulic Structure) Town Boundary Unknown 29-04: Bridge 32-1: --- District Boundaries Culvert - 1966 o - o - State/Town Highway Change Structure No. 201420D29414201 Structure No. 30009132-114231 --- Divided Highway Limits Structure Type: Unknown Length: 6' Under Clearance: 6.0' ---- Ghost Section Boundary Weight Limit: 0 ----- Federal Urban Area Limits Culvert - 1965 Facility Carried: I91 Structure No. 30009129-514201 Structure Type: CGMPP Scale: 1 INCH = 2,000 FEET Length: 6' Features Intersected: BROOK Under Clearance: 6.0' Inspection Date: 12/2019 Maintenance: State Facility Carried: I91 Travellane Structure Type: CGMPP Features Intersected: BROOK Roadway Inspection Date: 12/2019 **Road Widths** Lane Count Maintenance: State Bridge <mark>29-6</mark>: Culvert - 1965 Subbase Structure No. 30009129-614201 Length: 9' Curves Under Clearance: 10.0' Weight Limit: 0 Facility Carried: I91 Structure Type: CGMPP Grades Features Intersected: BLOOD BROOK Inspection Date: 12/2019 Maintenance: State **Guardrails** Bridge 29-7N: Culvert - 1965 **Rumblestrips** Structure No. 300091297N14201 Under Clearance: 8.0' Weight Limit: 0 **Speed Zone** Facility Carried: I91 Structure Type: CGMPP W SLEEVE Features Intersected: BROOK Curves: Head-on, FTC6 Inspection Date: 12/2019 Maintenance: State Curves: Overturn, FTC7 Culvert - 1965 Structure No. 30009129-914201 Length: 6' Curves: Run-off Road, FTC8 Under Clearance: 6.0' Weight Limit: 0 Facility Carried: I91 Structure Type: ACCGMPP Curves: Fixed Object, FTC9 Features Intersected: CATTLEPASS Inspection Date: 12/2019 Maintenance: State Curves: Night Run-off Road, FTC10 Bridge 29-10: Culvert - 1965 Structure No. 200091291014202 Interstate: Overturn, FTC11 Length: 21' Height: 100.0' Weight Limit: 0 Tangents: Head-on, FTC12 Facility Carried: I 91 ML Structure Type: TWIN CELL RC BOX Features Intersected: MILL BROOK Inspection Date: 5/2022 Tangents: Overturn, FTC13 Maintenance/Ownership: State Tangents: Run-off Road, FTC14 Stringer/multi-beam or girder - 1965 Structure No. 200091030N14202 Length: 220' Height: 100.0' Risk Width: 32.0' Primary Risk Under Clearance: 15.0' Weight Limit: 0 Facility Carried: I 91 ML Structure Type: 3 SP CONT ROLLED BM Medium Risk Features Intersected: I 91 OVER VT 131 Low Risk Inspection Date: 11/2022 Maintenance/Ownership: State Minimal Risk Bridge 30-1: Not a Focus Facility Culvert - 1966 Structure No. 30009130-114201 Length: 8' Under Clearance: 8.0' Weight Limit: 0 Facility Carried: I91

