VITANS Working to Get You There Vermont Agency of Transportation


Route Log and Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Section with questions or concerns.

DISTRICT TOWN ROUTE
5 MILTON US-2







STRUCTURE	DESCRIPTIONS

Bridge 15:
Culvert - 1960
Structure No. 300028001504101
Length: 17'
Under Clearance: 5.0'
Weight Limit: 0
Facility Carried: US2
Structure Type: CGMPPA
Features Intersected: LAKE CHAMPLAIN
Inspection Date: 9/2020
Maintenance: State

Stringer/multi-beam or girder - 1980
Structure No. 200028001704102
Length: 395'
Height: 100.0'
Width: 46.0'
Weight Limit: 0
Facility Carried: US 02 ML
Structure Type: 3 SP GIR W/ PIN+LINK
Features Intersected: LAMOILLE RIVER
Inspection Date: 5/2023
Maintenance/Ownership: State