

LŲDLOW

Route Log and Progress Chart


DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns. **DISTRICT TOWN ROUTE SPRINGFIELD** VT-11









STRUCTURE	DESCRIPTIONS
Bridge 55: Box beam or girders - multiple - 2007 Structure No. 200016005514182 Length: 58' Height: 100.0' Width: 40.0' Weight Limit: 0 Facility Carried: VT 11 ML Structure Type: PRECAST BOX BEAM Features Intersected: BROOK Surface: Bituminous Inspection Date: 6/2021 Maintenance/Ownership: State Bridge 56: Culvert - 1961 Structure No. 300134005614181 Length: 13' Under Clearance: 8.0' Weight Limit: 0 Facility Carried: VT11 Structure Type: CGMPPA Features Intersected: BROOK Inspection Date: 11/2020 Maintenance: State	Bridge 66: Stringer/multi-beam or girder - 1966 Structure No. 200016006614182 Length: 348' Height: 100.0' Width: 58.0' Weight Limit: 0 Facility Carried: VT 11 ML Structure Type: WELDED GIRDER Features Intersected: BLACK RIVER Surface: Bituminous Inspection Date: 6/2021 Maintenance/Ownership: State
Bridge 57: Culvert - 2021 Structure No. 200134005714182 Length: 32' Height: 100.0' Width: 40.0' Weight Limit: 0 Facility Carried: VT 11 ML Structure Type: PRECAST RIGID FRAME Features Intersected: BROOK Inspection Date: 6/2021 Maintenance/Ownership: State	
Unknown 57: Unknown Structure No. 300134005714181 Structure Type: Unknown	
Unknown 60: Unknown Structure No. 302500006014181 Structure Type: Unknown	
Bridge 61: Culvert - 1960 Structure No. 302500006114181 Length: 14' Under Clearance: 8.0' Weight Limit: 0 Facility Carried: VT11 Structure Type: CGMPPA Features Intersected: BROOK Inspection Date: 12/2022 Maintenance: State	
Bridge 62: Stringer/multi-beam or girder - 1937 Structure No. 202500006214182 Length: 192' Height: 100.0' Width: 46.0' Weight Limit: 0 Facility Carried: VT 11 ML Structure Type: 3 SPAN ROLLED BEAM Features Intersected: BLACK RIVER Surface: Bituminous Inspection Date: 6/2021 Maintenance/Ownership: City/Municipal	
Bridge 63A: Arch - deck - 1949 Structure No. 300016063A14181 Length: 24' Under Clearance: 7.0' Weight Limit: 0 Facility Carried: VT11 Structure Type: RC ARCH Features Intersected: BROOK Inspection Date: 11/2020 Maintenance: State	
Bridge 64: Stringer/multi-beam or girder - 1949 Structure No. 200016006414182 Length: 158' Height: 100.0' Width: 50.0' Weight Limit: 0 Facility Carried: VT 11 ML Structure Type: 2 SP CONT WLD PL GIR Features Intersected: BLACK RIVER Surface: Bituminous Inspection Date: 6/2021 Maintenance/Ownership: City/Municipal Bridge 65:	
Culvert - 1966 Structure No. 200016006514182 Length: 25'	







Crash Locations			
	Fatal Prop	perty Damage Only nown Crash Type	016 016
High Crash Locations (HCL's) Sections (& Intersections)			
	HCL No.	201 - 300 (21 - 30)	
	1 - 100 (1 - 10)	301 - 400 (31 - 40)	
	101 - 200 (11 - 20)	401 - 800 (41 - 113)	

Mileage by Functional Class By Sheet 6-2 4 - Minor Arterial 6-2 5 - Major Collector Page Total Mileage: 8.183 mi

Mileage by Town By Sheet 8.183 | SPRINGFIELD - V011-1418 | Ghost Section - (US-5, MM 2.239 to 3.064) 8.183 of 8.203 Page Total Mileage: 8.183 mi

TOWN DISTRICT SPRINGFIELD

Height: 100.0'

Weight Limit: 0

Inspection Date: 6/2021

Facility Carried: VT 11 ML Structure Type: TWIN CELL RC BOX

Features Intersected: SEAVER BROOK

Maintenance/Ownership: City/Municipal

ROUTE Date: 04/02/24 VT-11 1 of 2 ETE mileage: TWN mileage: 32.757 to 40.94 0.0 to 8.183