VITALS Working to Get You There Vermont Agency of Transportation

Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE


1 READSBORO Maj-0105

Bridge 32: Stringer/multi-beam or girder - 1919 Structure No. 200105003202092 Length: 127' Width: 37.3'

Surface: Bituminous Maintenance/Ownership: Town

Facility Carried: TR 02 FAS 105
Bridge Type: 2 SPAN ROLLED BEAM
Features Intersected: W. BR. DEERFIELD RIVER

DESCRIPTION BLOCK



								L			
Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet	Mileage by Functional Class By Sheet Mileage by Town By Sheet					
Retreatment Bituminous Gravel	├── + 1 ── ─ 7 ── ─ 12 ── ─ 17	curve left	← (ft)	(count)	0105 7 - Rural - Major Collector	1.600 READSBORO - S01050209	1.6 of 1.6	DISTRICT	TOWN	Date: 11/14/13	ROUTE
Resurface Concrete Bituminous Magazian Gravel	2 8 — 14 — 19	curve right						DISTRICT			
Unknown Bituminous Mix Bituminous Mix Plant Mix	6 —— 11 —— 16	Grades	Traffic Counters	Crash Locations							Maj-0105
Bituminous Mix Cold Plane and Skinny Mix Bituminous Bituminous Reclaimed Base and Rituminous	Speed Zones	grade up	(counter ID)	Fatal Property Damage Only					DEADCRORO	1 of 1	ETE mileage:
Bituminous Seal Concrete Concrete	SPEED	grade down	Ŷ	☐ Injury ☐ Unknown Crash Type				1	READSBORO	TWN mileage:	1.27 to 2.87
\ Concrete	25 30 35 40 45 50 55 60 65				T-1-1 M*1-	1 (00)	Tabl Miles and Carl			0.0 to 1.6	1