VITANS Working to Get You There Vermont Agency of Transportation

Crash Locations 2010


2008

Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

9 BARTON Min-0798




DESCRIPTION BLOCK

Bridge 61: Stringer/multi-beam or girder - 2007 Structure No. 101002006110021

Surface: Bituminous Maintenance/Ownership: Town

Length: 114'
Width: 24.0'
Facility Carried: C2003
Bridge Type: WELDED PLATE GIRDER
Features Intersected: WILLOUGHBY RIVER



Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet	t Mileage by Town By SI	heet				
Retreatment Bituminous Concrete Surface Treated	7 — 12 — 17	curve left	← (ft)	(count)	0798 8 - Rural - Minor Collector	0.898 BARTON - S07981002	0.898 of 0.898	DISTRICT	TOWN	Date: 11/15/13	ROUTE
Unknown Bituminous Gravel	6 — 11 — 16										Min-0798
Skinny Mix Skinny Mix Bituminous Cold Plane and Bituminous Reclaimed Base and Bituminous	Speed Zones Speed Speed (Speed (Spee	Grades	Traffic Counters (counter ID)	Crash Locations Fatal □ Property Damage Onl □ Injury □ Unknown Crash Type	у			9	BARTON	1 of 1 TWN mileage:	ETE mileage:
Concrete	25 30 35 40 45 50 55 60 65	grade down		Injury Onknown Clash Type		otal Mileage: 0 909 mi	Total Mileage: 0 808 mi			0.0 to 0.898	0.0 to 0.898