## **DISTRICT TOWN ROUTE DRAFT Route Log Progress Chart** Please Note: Errors and Omissions May Exist. VT-100 **PLYMOUTH** Contact the VTrans Mapping Unit with questions or concerns. Base Map KILLINGTON 1 in = 0.5 miles Stick Diagram Primary Structures Secondary Structures Stations (Feet) +++++ Railroad Crossings Divided State Highway State Highway Divided Class 1 Town Highway ——— Class 1 Town Highway --- Town Boundary – – District Boundaries - O State/Town Highway Change --- Divided Highway Limits ---- Ghost Section Boundary Streams Scale: 1in = 2000 FEETTravellane Roadway Road Widths Lane Count 3" Crushed Stone P.M. 18" Crushed Rock Subbase -7 30' 7 Curves Grades **Historic Projects** 1984: HMA 2456 Maintenance Garage District 3 - Mendon Garage **Traffic Counters Functional Class** Speed Zone 1200 1200 **AADT Counts** 1200 1100 2012 Crash Locations 2010 2008 **Road Widths** Mileage by Functional Class By Sheet Mileage by Town By Sheet

013-3 6 - Rural - Minor Arterial

Fatal Property Damage Only

■ Injury □ Unknown Crash Type

0.726 PLYMOUTH - V100-1412

Total Mileage: 0.726 mi

0.726 of 9.726

Total Mileage: 0.726 mi

**DISTRICT** 

**DESCRIPTION BLOCK** 

Culvert 114: Culvert - 1971

Length: 7' Under Clearance: 7.0'

Facility Carried: VT100

Bridge Type: CGMPP

Length: 8' Under Clearance: 8.0'

Facility Carried: VT100

Bridge Type: CGMPP

Maintenance: State

Maintenance: State

Culvert 115: Culvert - 1971

Structure No. 300013011414121

Structure No. 300013011514121

Features Intersected: RESERVOIR BROOK

Features Intersected: RESERVOIR BROOK

Speed Zones

TIMIT LIMIT LIMIT

Resurface Concrete
Unknown Bituminous Macadam

Skinny Mix

Skinny Mix

Bituminous Seal

Cold Plane and
Bituminous
Concrete

Plant Mix

Reclaimed Base and Bituminous

Concrete

curve left