
Trans Working to Get You There Vermont Agency of Transportation


Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.


DISTRICT TOWN ROUTE

8 WATERVILLE VT-109





Tra	avellane -	20	18		<u> </u>	
Tra Ro ad Widths Lane	oadway 4	24 28 30 24 26 21	22			
	o Count		2			
au Wiutiis Lain	Base				'	
c	Base Subbase		,			
	bubbase					
Curves	_	7	13 6	6 6	7	
Cui ves	7	6	5 5	6 9 —	6	
			<u> </u>			
Grades			<u>-7.0</u>	-6.0	-7.0	
Grades	+9.0		+8.0	+7.0		
			,			
			,			



\	1947: Unknown	1957: ST 202-L	
Maintanana Car	12.0	District 8 - Cambridge Garage	
Maintenance Gar	age		
			S6L119
Crash Locations	´S		
Functional Clas	ss ———	7	
Speed Zone		SPEED SPEE	
<u> </u>			
	2012 300 820 → <	850	
	800 1300	850	
	2011		
AADT Counts	2010 300 1800 ★ ◆ ▶ ◆	840	
	2009 400 1700 ★ ★ ★ ★ ★	900	
	2009 ★< →<		
	2008	950	
	2012		
	2012		
	2011		
Crash Locations			
Crash Locations	2010		
	2009		
		_	
	2008		

DESCRIPTION BLOCK	,

Bridge 4:
Box beam or girders - multiple - 1998
Structure No. 200282000408092
Length: 134'
Width: 30.0'
Facility Carried: VT 00109 ML
Bridge Type: CONT CONC PS BOX BM
Features Intersected: N. BRANCH LAMOILLE R
Surface: Bituminous
Maintenance/Ownership: State

Culvert 5:
Culvert - 1957
Structure No. 300282000508091
Length: 6'
Under Clearance: 6.0'
Facility Carried: VT109
Bridge Type: ACCGMP
Features Intersected: BROOK
Maintenance: State

Culvert 6:
Culvert - 1957
Structure No. 300282000608091
Length: 7'
Under Clearance: 7.0'
Facility Carried: VT109
Bridge Type: ACCGMP
Features Intersected: BROOK
Maintenance: State