DISTRICT TOWN ROUTE DRAFT Route Log Progress Chart Please Note: Errors and Omissions May Exist. **WHITINGHAM** VT-112 Contact the VTrans Mapping Unit with questions or concerns. Base Map HALIFAX WHITINGHAM WILMINGTON WHITINGHAM 1 in = 2,000 feet Stick Diagram Primary Structures Secondary Structures Stations (Feet) +++++ Railroad Crossings Divided State Highway State Highway Divided Class 1 Town Highway ——— Class 1 Town Highway --- Town Boundary – – District Boundaries - State/Town Highway Change --- Divided Highway Limits ---- Ghost Section Boundary >>>> Streams 6422 7182 7622 7807 8171 2228 2793 3198 Scale: 1in = 2000 FEETTravellane Roadway Road Widths Lane Count 18" Gravel Subbase 22.1 5 8 7 8 ____ 35 Curves Grades **Historic Projects** 1939: PWA 1092-F-3 1953: ST 24-S 1936: ST District 1 - Wilmington Garage Maintenance Garage **Traffic Counters Functional Class** Speed Zone 1600 1700 1700 **AADT Counts** 1600 1500 2012 Crash Locations 2010

Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet		Mileage by Town By Sheet					
Retreatment Bituminous Gravel	├── + 1 ── ─ 7 ── ─ 12 ── ─ 17	curve left	← (ft)	(count)	013-1 6 - Rural - Minor Arterial	1.604	WHITINGHAM - V112-1321	1.604 of 1.604	DISTRICT	TOWN	Date: 11/15/13	ROUTE
Resurface Concrete Surface Treated Gravel	2 8 — 14 — 19	curve right							DISTRICT	101111		1.0012
Macadam	6 — 11 — 16			.								VT-112
Bituminous Mix Cold Plane and Reclaimed Base		Grades	Traffic Counters	Crash Locations							1 of 1	1
Skilling Wilx Bituminous and Bituminous	Speed Zones	grade up	(counter ID)	Fatal Property Damage Only					4	WHITINGHAM		ETE mileage:
Concrete Concrete	SPEED	grade down	Y	■ Injury □ Unknown Crash Type						WIIIIIIIIIII	TWN mileage:	5.846 to 7.45
Concrete	25 30 35 40 45 50 55 60 65				Total	Mileage: 1.604 mi		Total Mileage: 1.604 mi			0.0 to 1.604	1

DESCRIPTION BLOCK

Bridge 11: Stringer/multi-beam or girder - 1934 Structure No. 200013001113212

Features Intersected: EAST BRANCH OF NORTH R.

Facility Carried: VT 00112 ML Bridge Type: ROLLED BEAM

Maintenance/Ownership: State

Structure No. 300013001213211

Features Intersected: SPRAGUE BROOK

Facility Carried: VT 00112 ML
Bridge Type: ROLLED BEAM
Features Intersected: EAST BRANCH OF NORTH R.

Features Intersected: EAST BRANCH OF NORTH R.

Stringer/multi-beam or girder - 1939 Structure No. 200013001313212

Surface: Bituminous

Under Clearance: 9.0'

Bridge Type: CGMPA

Maintenance: State

Surface: Bituminous

Maintenance/Ownership: State

Facility Carried: VT 00112 ML Bridge Type: ROLLED BEAM

Maintenance/Ownership: State

Structure No. 300013001513211

Under Clearance: 4.0'
Facility Carried: VT112
Bridge Type: CONCRETE SLAB

Features Intersected: BROOK

Surface: Bituminous

Maintenance: State

Surface: Bituminous

Bridge 14: Stringer/multi-beam or girder - 1939 Structure No. 200013001413212

Facility Carried: VT112

Culvert 12: Culvert - 1965

Length: 15'

Length: 84' Width: 26.8'

Length: 88' Width: 29.3'

Width: 29.0'

Length: 75' Width: 24.3'

2008