

Route Log Progress Chart

DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT ROUTE TOWN VT-155 **MOUNT HOLLY**





DESC	RTP	ΓΤΟΝ	BI	OCK

Culvert 4: Culvert - 1964 Structure No. 300133000411121 Length: 10' Under Clearance: 4.0' Facility Carried: VT155 Bridge Type: RC BOX Features Intersected: BROOK Maintenance: State

Culvert 6: Culvert - 1965 Structure No. 300133000611121 Length: 6' Under Clearance: 6.0' Facility Carried: VT155 Bridge Type: A.C.C.G.M.P Features Intersected: BROOK Maintenance: State


Culvert 7: Culvert - 1969 Structure No. 300133000711121 Length: 15' Under Clearance: 11.5' Facility Carried: VT155 Bridge Type: CGMPPA Features Intersected: MILL RIVER Maintenance: State

Culvert 9: Culvert - 1959 Structure No. 300133000911121 Length: 8' Under Clearance: 5.0' Facility Carried: VT155 Bridge Type: RC BOX Features Intersected: BROOK Maintenance: State

Culvert 11: Culvert - 1919 Structure No. 300133001111121 Length: 16' Under Clearance: 9.0' Facility Carried: VT155 Bridge Type: MULTIPLATE PIPE ARCH Features Intersected: MEADOW BROOK

Stringer/multi-beam or girder - 1900 Structure No. 200133001211122 Length: 41' Width: 30.8' Facility Carried: VT 00155 ML Bridge Type: ROLLED BEAM Features Intersected: MILL RIVER Surface: Bituminous Maintenance/Ownership: State

Girder and floorbeam system - 1903 Structure No. 200133001411122 Length: 162' Facility Carried: RAILROAD Bridge Type: RIVETED TWO GIRDER Features Intersected: GMRR OVER MILL R. VT 155



		A	ADT
		_	(count)
			•
	Cı	ash	Locations
	Fatal		Property Damage On
	Injury		Unknown Crash Type

		Mileage by Functional Class By Sheet								
	01	L33	7 - Rural - Major Collector		7.603					
ly	_									
				Total Mileage:	7.603 mi					

ROUTE

VT-155

ETE mileage:

2.275 to 9.878