Trans Working to Get You There Vermont Agency of Transportation

Route Log Progress Chart

DRAFT

Please Note: Errors and Omissions May Exist.

Contact the VTrans Mapping Unit with questions or concerns.


DISTRICT TOWN ROUTE

8 HIGHGATE Maj-0300



DESCRIPTION BLOCK

Bridge D99:
Stringer/multi-beam or girder - 1965
Structure No. 2006090D9906091
Length: 285'
Width: 29.4'
Under Clearance: 16.33'
Weight Limit: 0
Facility Carried: TR 00TH1
Bridge Type: 5 SPAN ROLLED BEAM
Features Intersected: TH NO 1 OVER I 89
Surface: Bituminous
Maintenance/Ownership: State



Left	← (ft)	(count) →	0300 7 - Rural - Major Collector	3.580	HIGHGATE - S03000609	3.58 of 3.58	DISTRICT	TOWN	Date: 05/21/14	ROUTE
								101111		
					ı		1			_
Grades	Traffic Coun	ters Crash Locations							1 06 1	Maj-030
nesgrade	up (counter ID)	Fatal Property Damage	Only					UTCUCATE		ETE mileage
ED SPEED SPEED SPEED SPEED GRADE	down Y	Injury Unknown Crash Ty	ype				•	HIGHGATE		ETE mileage 0.0 to 3.58
SPE	onesgrade u	Dnes grade up (counter ID)	Dines	DNes grade up (counter ID) Fatal Property Damage Only Injury Unknown Crash Type	Dines grade up (counter ID) Fatal Property Damage Only Injury Unknown Crash Type	Dines grade up (counter ID) Fatal Property Damage Only Injury Unknown Crash Type	Dines grade up (counter ID) Fatal Property Damage Only Injury Unknown Crash Type	grade up (counter ID) grade down (counter ID) Fatal Property Damage Only Injury Unknown Crash Type	The speed of the s	BIGHGATE Fatal Property Damage Only Injury Unknown Crash Type