VITANS Working to Get You There Vermont Agency of Transportation

Route Log Progress Chart


DRAFT

Please Note: Errors and Omissions May Exist.

Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

2 SPRINGFIELD Min-0562



DESCRIPTION BLOCK

Stringer/multi-beam or girder - 1935 Structure No. 101418004514181

Bridge Type: CONC ENCASED ROLL BM

Bridge Type: CONC ENCASED ROLL BM

Bridge Type: CONC ENCASED ROLL BM Features Intersected: GREAT BROOK

Length: 27' Width: 18.0'

Surface: Gravel

Length: 26'

Length: 34' Width: 26.7'

Facility Carried: C2010

Facility Carried: C2010

Surface: Bituminous

Features Intersected: BROOK

Maintenance/Ownership: Town

Stringer/multi-beam or girder - 1937

Structure No. 101418004714181

Maintenance/Ownership: Town

Structure No. 101418005814181

Features Intersected: BROOK

Maintenance/Ownership: Town

Surface: Bituminous

Facility Carried: C2006 Bridge Type: TBEAM WIDE W/ ROL BM

Facility Carried: C2010

Surface: Bituminous


Bridge <mark>58</mark>: Tee Beam - 1933

Length: 28' Width: 29.7'

Features Intersected: BROOK

Maintenance/Ownership: Town

Bridge <mark>46</mark>: Stringer/multi-beam or girder - 1937 Structure No. 101418004614181



TOWN	Date: 05/21/14	ROUTE
PRINGFIELD	1 of 1 TWN mileage:	Min-0562 ETE mileage: 4.09 to 6.36