

Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

1 BENNINGTON Min-1028




DESCRIPTION BLOCK

Bridge 49: Stringer/multi-beam or girder - 1975 Structure No. 201028004902022

Length: 51'
Width: 28.2'
Facility Carried: CITY HUNT EXT
Bridge Type: ROLLED BEAM
Features Intersected: WALLOOMSAC RIVER

Surface: Bituminous Maintenance/Ownership: City/Municipal



										L		
Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Shee	t	Mileage by Town By Sheet					
Retreatment Bituminous Gravel	├────────────────────────────────────	Left	← (ft)	(count)	1028 17 - Urban - Collector	0.270	BENNINGTON - S10280202	0.27 of 0.27	DISTRICT	TOWN	Date: 05/21/14	ROUTE
Resurface Concrete Surface Treated	2 8 — 14 — 19	Right							DISTRICT		Date: 05/21/14	ROOLE
Unknown Bituminous Macadam Plant Mix	6 11 16											Min-1028
Cold Diagonal	Consol Zones	Grades	Traffic Counters	Crash Locations							1 of 1	
Skinny Mix Skinny Mix Bituminous Concrete Reclaimed Base and Bituminous Concrete Concrete	Speed Zones	grade up	(counter ID)	Fatal Property Damage Only					1 1	BENNINGTON		ETE mileage:
Bituminous Seal Concrete	SPEED	grade down	Į [†]	Injury Unknown Crash Type					-		TWN mileage:	0.0 to 0.27
Concrete	25 30 35 40 45 50 55 60 65				Т	otal Mileage: 0.270 mi		Total Mileage: 0.27 mi			0.0 to 0.27	