## VITANS Working to Get You There Vermont Agency of Transportation


## **Route Log Progress Chart**

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

**DRAFT** 

DISTRICT TOWN ROUTE

1 WHITINGHAM VT-112



**DESCRIPTION BLOCK** 

Stringer/multi-beam or girder - 1934 Structure No. 200013001113212

Features Intersected: E. BR. OF NORTH RIVER

Facility Carried: VT 00112 ML Bridge Type: ROLLED BEAM

Maintenance/Ownership: State

Structure No. 300013001213211

Features Intersected: SPRAGUE BROOK

Features Intersected: E. BR. OF NORTH RIVER

Features Intersected: E. BR. OF NORTH RIVER

Stringer/multi-beam or girder - 1939 Structure No. 200013001313212

Facility Carried: VT 00112 ML

Bridge Type: ROLLED BEAM

Maintenance/Ownership: State

Facility Carried: VT 00112 ML Bridge Type: ROLLED BEAM

Maintenance/Ownership: State

Structure No. 300013001513211

Facility Carried: VT112
Bridge Type: CONCRETE SLAB

Features Intersected: BROOK

Surface: Bituminous

Under Clearance: 4.0'

Surface: Bituminous Maintenance: State

Bridge 14: Stringer/multi-beam or girder - 1939 Structure No. 200013001413212

Surface: Bituminous

Under Clearance: 9.0' Facility Carried: VT112

Bridge Type: CGMPA

Maintenance: State

Surface: Bituminous

Culvert 12: Culvert - 1965


Length: 15'

Length: 84' Width: 26.8'

Length: 88' Width: 29.3'

Width: 29.0'

Length: 75' Width: 24.3'



Date: 05/22/14	ROUTE