
VTrans Working to Get You There Vermont Agency of Transportation

Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

5 JERICHO VT-117



DESCRIPTION BLOCK

Culvert 5:
Culvert - 1957
Structure No. 300224000504091
Length: 10'
Under Clearance: 11.0'
Facility Carried: VT117
Bridge Type: MULTIPLATE PIPE
Features Intersected: BROOK
Maintenance: State

Culvert 6:
Culvert - 1957
Structure No. 300224000604091
Length: 6'
Under Clearance: 6.0'
Facility Carried: VT117
Bridge Type: CGMP
Features Intersected: BROOK
Maintenance: State

Bridge 7:
Stringer/multi-beam or girder - 1979
Structure No. 200224000704092
Length: 66'
Width: 40.0'
Facility Carried: VT 00117 ML
Bridge Type: ROLLED BEAM
Features Intersected: MILL BROOK
Surface: Bituminous
Maintenance/Ownership: State

Culvert 8:
Culvert - 1957
Structure No. 300224000804091
Length: 6'
Under Clearance: 6.0'
Facility Carried: VT117
Bridge Type: CGMPP
Features Intersected: BROOK
Maintenance: State

		Contact the VTrans Mapping Unit with questions or concerns. 5 JERICHO VT-117
Base Map	ESSEX CENTER U.C.	JERICHO RICHMOND WILLISTON
Stick Diagram Town Boundary Village/UC Boundaries	OHOUGH THE TOTAL	
District Boundaries State/Town Highway Change Divided Highway Limits Ghost Section Boundary FAU Limits Streams Town Center Primary Structures Secondary Structures Stations (Feet) Railroad Crossings Divided State Highway State Highway	BLOOK BARBER FARM RD (TH-1) DBsc. DBsc.	
Divided Class 1 Town Highway Class 1 Town Highway Scale: 1 INCH = 2000 FEET	0 1 1 1 1 1 1 2 1 1 2 1 1 1 1 1 1 1 1 1	
Travellane Road Widths Lane Count Base Subbase	26 27 22 26 24	
	6 8 3 3 4 5 10 6 8 30	
Grades		
	1995: STP 9472(1)S 1985: RS 0224(3) 1980: BRS 0224(2) 1972: Unknown 1972: Unknown	
Maintenance Garage	District 5 - Colchester Garage	
Traffic Counters	О О О О О О О О О О О О О О О О О О О	
Functional Class	6	
Speed Zone		
2012 2011 AADT Counts 2010 2009 2008	5200 4900 4500 5100 4700	
2012 2011 Crash Locations 2010 2009 2008		
-	<u> </u>	

Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet		Mileage by Town By Sheet					
Retreatment Bituminous Gravel	├── + 1 <mark>───</mark> 7 ─── 12 <u></u> ─── 17	Left	← (ft)	(count)	035-1 6 - Rural - Minor Arterial	2.893	JERICHO - V117-0409	2.893 of 2.893	DISTRICT	TOWN	Date: 05/22/14	ROUTE
Resurface Concrete Surface Treated Gravel	2 8 — 14 — 19	Right							DISTRICT	101111	Date: 05/22/14	
Unknown Bituminous Mix Cold Plane and	6 — 11 — 16	Cuadaa	Traffic Counters	Crash Locations								VT-117
Cold Plane and Reclaimed Base	Speed Zones	Grades ——		_ Clash Locations							1 of 1	
Bituminous and Bituminous	Speed Zolles	grade up	(counter ID)	Fatal Property Damage Only						JERICHO	TWN mileage:	ETE mileage: