
## VITANS Working to Get You There Vermont Agency of Transportation

## **Route Log Progress Chart**

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE


6 STOWE Maj-0236



## **DESCRIPTION BLOCK**

Bridge 5:
Stringer/multi-beam or girder - 1951
Structure No. 200236000508082
Length: 99'
Width: 24.2'
Facility Carried: TR 01 FAS 236
Bridge Type: ROLLED BEAM
Features Intersected: LITTLE RIVER
Surface: Bituminous
Maintenance/Ownership: Town

Bridge 53:
Stringer/multi-beam or girder - 1952
Structure No. 200236005308082
Length: 64'
Width: 23.9'
Facility Carried: TR 5 FAS 236
Bridge Type: ROLLED BEAM
Features Intersected: WEST BRANCH LITTLE RIVER
Maintenance/Ownership: Town



Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet	Mileage by Tow	vn By Sheet				
Retreatment Bituminous Concrete Surface Treated	7 — 12 — 17	curve left	<b>←</b> (ft)	← (count)	0236 7 - Rural - Major Collector	3.870 STOWE - S02360808	3.87 of 3.87	DISTRICT	TOWN	Date: 04/01/14	ROUTE
Unknown  Bituminous  Macadam  Plant Mix	6 — 11 — 16	Grades	Traffic Counters	Crash Locations						_	Maj-0236
Skinny Mix  Skinny Mix  Bituminous  Congrete and Bituminous	Speed Zones	grade up	(counter ID)	Fatal Property Damage Only				6	STOWE	1 of 1 TWN mileage:	ETE mileage:
Bituminous Seal Concrete Concrete  Concrete	SPEED	grade down	1	Injury Unknown Crash Type	Total I	Mileage: 3.870 mi	Total Mileage: 3.87 mi			0.0 to 3.87	0.0 to 3.87