
VITANS Working to Get You There Vermont Agency of Transportation

Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

9 COVENTRY Min-0802



DESCRIPTION BLOCK

Bridge 8: Stringer/multi-beam or girder - 1951 Structure No. 101005000810051

Features Intersected: BARTON RIVER

Maintenance/Ownership: Town

Structure No. 201005D08S10051

Bridge Type: STEEL RIGID FRAME Features Intersected: TH NO 3 OVER I 91

Features Intersected: TH NO 3 OVER I 91

Under Clearance: 18.08' Facility Carried: TR 00TH3

Surface: Bituminous Maintenance/Ownership: State

Structure No. 201005D08N10051

Maintenance/Ownership: State

Under Clearance: 19.08' Facility Carried: TR 00TH3 Bridge Type: STEEL RIGID FRAME

Surface: Bituminous

Length: 99' Width: 20.0'

Facility Carried: C2001 Bridge Type: ROLLED BEAM


Surface: Bituminous

Bridge <mark>D08S</mark>: Frame - 1971

Length: 124' Width: 31.4'

Bridge <mark>D08N</mark>: Frame - 1971

Length: 124' Width: 31.4'



	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet	Mileage by Town By She	et				
Retreatment Resurface Bituminous Concrete Surface Treated Gravel Gravel	7 — 12 — 17 — 2 — 8 — 14 — 19	curve left	← (ft)	(count)	0802 8 - Rural - Minor Collector	2.150 COVENTRY - S08021005	2.15 of 2.15	DISTRICT	TOWN	Date: 04/01/14	ROUTE
ninous Mix Cold Plane and Bituminous Concrete Concrete Plant Mix Reclaimed Base and Bituminous Concrete	Speed Zones Speed Zones Speed Spee	Grades grade up grade down	Traffic Counters (counter ID)	Crash Locations ■ Fatal □ Property Damage Only □ Injury □ Unknown Crash Type				9	COVENTRY	1 of 1 TWN mileage: 0.0 to 2.15	Min-0802 ETE mileage: 0.0 to 2.15