


## **Route Log Progress Chart**

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

**DRAFT** 

DISTRICT TOWN ROUTE

1 BENNINGTON Min-1063




**DESCRIPTION BLOCK** 

Bridge <mark>29</mark>: Stringer/multi-beam or girder - 1956 Structure No. 100202002902021

Surface: Bituminous Maintenance/Ownership: Town

Length: 43'
Width: 29.7'
Facility Carried: C3017
Bridge Type: ROLLED BEAM
Features Intersected: FURNACE BROOK



Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Shee	t	Mileage by Town By Sheet					
Retreatment Bituminous Concrete Surface Treated	├── <del>+ </del> 1 <del>───</del> 7 <del>───</del> 12 ─── 17	curve left	<b>←</b> (ft)	← (count)	1063 17 - Urban - Collector	0.225	BENNINGTON - S10630202	0.225 of 0.225	DISTRICT	TOWN	Date: 04/01/14	ROUTE
Unknown Bituminous Gravel	2 8 — 14 — 19											Min-1063
Cold Plane and Skinny Mix Bituminous  Reclaimed Base and Bituminous	Speed Zones	<b>Grades</b>	Traffic Counters (counter ID)	Crash Locations  ■ Fatal □ Property Damage Only					_	DENINTRACTON	1 of 1	ETE mileage:
Concrete Concrete  Concrete	SPEED	grade down	Ŷ	☐ Injury ☐ Unknown Crash Type					1	BENNINGTON	TWN mileage: 0.0 to 0.225	0.0 to 0.225
Concrete	25 50 55 40 45 50 55 60 65				7	otal Mileage: 0.225 mi		Total Mileage: 0.225 mi			0.0 to 0.223	