


Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.


DISTRICT TOWN ROUTE

1 BENNINGTON NSH-9025



DESCRIPTION BLOCK

Bridge 1:
Stringer/multi-beam or girder - 1973
Structure No. 200019016S02022
Length: 140'
Height: 0.0'
Weight Limit: 0
Facility Carried: US 00007 ML
Bridge Type: WELDED PLATE GIRDER
Features Intersected: US 7 OVER BENN SH



Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet		Mileage by Town By Sheet					
Retreatment Resurface Unknown Bituminous Concrete Surface Treated Gravel Gravel	7 — 12 — 17 — 2 — 8 — 14 — 19	curve left	← (ft)	(count)	119-1 6 - Rural - Minor Arterial	0.236 BENNINGTO	ON - S90250202W	0.236 of 0.236	DISTRICT	TOWN	Date: 04/02/14	ROUTE
ituminous Mix Cold Plane and kinny Mix Bituminous Bituminous ARCEIaimed Base and Bituminous	6 —— 11 —— 16 Speed Zones	Grades grade up	Traffic Counters (counter ID)	Crash Locations Fatal Property Damage Only					_	DENNINGTON	1 of 1	NSH-902
Bituminous Seal Concrete Concrete Concrete	SPEED SPEED SPEED SPEED SPEED LIMIT	SPEED	Ŷ	☐ Injury ☐ Unknown Crash Type	Total	Mileage: 0.236 mi	0.236 mi Total Mileage: 0.236 m	Total Mileage: 0.236 mi	1	BENNINGTON	TWN mileage: 0.0 to 0.236	ETE mileage: 0.0 to 0.236