Route Log and Progress Chart

DISTRICT DRAFT

TOWN

ROUTE


Maj-0114


ROUTE

Maj-0114

ETE mileage:

1.48 to 10.48





STRUCTURE	DESCRIPTIONS

Stringer/multi-beam or girder - 1982 Structure No. 200114014A02152 Length: 108' Width: 34.0' Under Clearance: 16.42' Facility Carried: TR 03 FAS 114 Bridge Type: WELDED PLATE GIRDER Features Intersected: US 7 UNDER FAS 114 TR3 Surface: Bituminous Maintenance/Ownership: State


Stringer/multi-beam or girder - 2006 Structure No. 200114001402152 Length: 89' Width: 21.6' Facility Carried: TR 03 FAS 114 Bridge Type: CURVED WLD PLT GIRD Features Intersected: ROARING BRANCH BROOK Maintenance/Ownership: Town


Bridge 16: Box beam or girders - multiple - 2015 Structure No. 200114001602152 Length: 75' Width: 16.0' Facility Carried: TR 03 FAS 114 FH6
Bridge Type: PRESTRES CONC BOX BM Features Intersected: ROARING BRANCH BROOK Surface: Concrete Maintenance/Ownership: Town


Bridge 15: Stringer/multi-beam or girder - 1939 Structure No. 200114001502152 Length: 94' Width: 11.8' Facility Carried: TR 03 FAS 114 FH6
Bridge Type: ROLLED BEAM Features Intersected: ROARING BRANCH BROOK Maintenance/Ownership: Town


Stringer/multi-beam or girder - 1935 Structure No. 200114001702152 Facility Carried: TR 03 FAS 114 FH6 Bridge Type: ROLLED BM W TIM DK
Features Intersected: ROARING BRANCH BROOK Surface: Timber Maintenance/Ownership: Town


Stringer/multi-beam or girder - 1966 Structure No. 200114001202152 Width: 24.1' Facility Carried: TR 03 FAS 114 FH6 Bridge Type: ROLLED BEAM
Features Intersected: ROARING BRANCH BROOK Maintenance/Ownership: Town











Mileage by Town By Sheet