Route Log and Progress Chart

DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns. **DISTRICT TOWN ROUTE GRAFTON** Maj-0126



Bridge 15G: Stringer/multi-beam or girder - 1939 Structure No. 200126015G13062

Facility Carried: TR 01 FAS 126

Features Intersected: SAXTONS RIVER

Facility Carried: TR 01 FAS 126
Bridge Type: PRECAST CONC BOXBEAM

Features Intersected: SAXTONS RIVER

Bridge Type: ROLLED BEAM

Maintenance/Ownership: Town

Structure No. 200126001013062

Maintenance/Ownership: Town

Surface: Bituminous

Surface: Bituminous

Length: 99' Width: 22.2'


Bridge <mark>10</mark>: Slab - 1977

Length: 52'


Width: 26.6'





STRUCTURE DESCRIPTIONS




Bridge 13G:
Stringer/multi-beam or girder - 1939
Structure No. 200126013G13062
Length: 74'
Width: 22.1'
Facility Carried: TR 01 FAS 126
Bridge Type: ROLLED BEAM
Features Intersected: SAXTONS RIVER
Surface: Bituminous
Maintenance/Ownership: Town
Bridge 12:
Stringer/multi-beam or girder - 1939
Structure No. 200126001213062
Structure 190, 200 (2000 (213002)
Length: 75'
Width: 23.9'
Facility Carried: TR 01 FAS 126
Bridge Type: ROLLED BEAM
Features Intersected: SAXTONS RIVER
Surface: Bituminous
Maintenance/Ownership: Town
Maintenance of Micronip. 10Mi









AADT				
(count)				
Crash Locations				
Fatal	☐ Property Damage Only			
Injury	Unknown Crash Type			

Mileage by Functional Class By Sheet						
0126	5 - Major Collector	5.120				
	Page Total Mileage:	5.700 mi				

	Mileage by Town By Sheet		
	GRAFTON - S01261306 Ghost Section - (Maj-0125, MM 4.140 to 0.260)	5.7 of 5.89	
_	Pag	e Total Mileage: 5.7 mi	

DISTRICT

ROUTE

ETE mileage:

2.41 to 8.11