
Route Log and Progress Chart

DISTRICT DRAFT Please Note: Errors and Omissions May Exist. **SWANTON** Contact the VTrans Mapping Section with questions or concerns.

TOWN ROUTE Min-0788



Min-0788



STRUCTURE	DESCRIPTIONS
Bridge 94S: Stringer/multi-beam or girder - 1967 Structure No. 200089094S06152 Length: 116' Width: 37.9' Under Clearance: 15.5' Facility Carried: I 00089 ML Bridge Type: WELDED PLATE GIRDER Features Intersected: I 89 OVER TH NO Surface: Bituminous Maintenance/Ownership: State Bridge 94N: Stringer/multi-beam or girder - 1967 Structure No. 200089094N06152 Length: 106' Width: 37.9' Under Clearance: 14.17' Facility Carried: I 00089 ML Bridge Type: WELDED GIRDER Features Intersected: I 89 OVER TH NO Surface: Bituminous Maintenance/Ownership: State Bridge 4: Stringer/multi-beam or girder - 1957 Structure No. 100615000406151 Length: 29' Width: 25.0'	
Facility Carried: C2003 Bridge Type: ROLLED BEAM Features Intersected: HUNGERFORD BF Surface: Bituminous Maintenance/Ownership: Town	ROOK

Curves	Road W
degrees) Right	← (ft)
Grades	Traffic C
percent) grade up grade down	(counte

S	AADT	
	(count)	
ers	Crash Locations	
	Fatal Property Damage On	
	Injury Unknown Crash Type	
T 05000		

DT		
nt)	0788	6
ocations Operty Damage Only known Crash Type		

Mileage by Functional Class By Sheet			
788	6 - Minor Collector		2.850
		Page Total Mileage:	2.850 m

	Mileage by Town By Sheet		_
2.850	SWANTON - S07880615	2.85 of 2.85	
850 mi		Page Total Mileage: 2.85 mi	

DISTRICT	TOWN	Date: 11/11/16
8	SWANTON	1 of 1 TWN mileage: 0.0 to 2.85