Trans Working to Get You There Vermont Agency of Transportation


Route Log and Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Section with questions or concerns.

DISTRICTTOWNROUTE5BOLTONUS-2







STRUCTURE	DESCRIPTIONS

Culvert 34:
Culvert - 1964
Structure No. 300284003404011
Length: 11'
Under Clearance: 11.0'
Facility Carried: US2
Bridge Type: MULTI PLATE PIPE
Features Intersected: DUCK BROOK
Maintenance: State

Bridge 51S:
Stringer/multi-beam or girder - 1961
Structure No. 200089051S04012
Length: 453'
Width: 32.0'
Under Clearance: 16.42'
Facility Carried: I 00089 ML
Bridge Type: 6 SPN CONT WGIR/RB
Features Intersected: I 89 OVER US2+JOINER BK
Surface: Bituminous
Maintenance/Ownership: State

Bridge 51N:
Stringer/multi-beam or girder - 1961
Structure No. 200089051N04012
Length: 364'
Width: 32.0'
Under Clearance: 14.75'
Facility Carried: I 00089 ML
Bridge Type: 5 SPN CONT WGIR/RB
Features Intersected: I 89 OVER US2+JOINER BK
Surface: Bituminous
Maintenance/Ownership: State

Stringer/multi-beam or girder - 1961 Structure No. 200284003704012 Length: 90' Width: 35.0' Facility Carried: US 00002 ML Bridge Type: ROLLED BEAM Features Intersected: JOINER BROOK Surface: Bituminous Maintenance/Ownership: State