
Route Log and Progress Chart

DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.


DISTRICT TOWN ROUTE VT-30 WINHALL










- `	
STRUCTURE	DESCRIPTIONS
oridge 43: otringer/multi-beam or girder - 1938 otructure No. 200015004302162 ength: 170' Vidth: 39.5' facility Carried: VT 00030 ML oridge Type: 3 SPN CONT ROLLED BM eatures Intersected: WINHALL RIVER ourface: Bituminous Maintenance/Ownership: State	
Culvert 45: Culvert - 1956 Structure No. 300015004502161 ength: 12' Inder Clearance: 7.0' facility Carried: VT30 stridge Type: CGMPPA features Intersected: BROOK Maintenance: State	
Culvert 46: Culvert - 1956 Structure No. 300015004602161 ength: 12' Inder Clearance: 5.67' facility Carried: VT30 Fridge Type: CGMPPA features Intersected: BROOK faintenance: State	
Culvert 47: Culvert - 2015 Culvert - 2015 Culvert - 2015 Culvert - 2015 Culvert - 2016 Culvert -	
Culvert 52: Culvert - 2015 Culvert - 2016 Culvert -	











dths	AADT			
→	(count)			
unters	Crash Locations			
	■ Fatal □ Property Damage C			
D)	☐ Injury ☐ Unknown Crash Typ			





	Mileage by Town By Sheet]
	WINHALL - V030-0216 Ghost Section - (VT-11, MM 3.153 to 0.000)	7.659 of 7.659	
_	Page	Total Mileage: 7.659 mi	

DISTRICT	TOWN	Date: 11/14/16	ROUTE VT-30
1	WINHALL	1 of 2 TWN mileage: 0.0 to 7.659	ETE mileage: 31.815 to 39.474