

Route Log and Progress Chart

DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.





Stringer/multi-beam or girder - 1973 Structure No. 200110005E02022

Bridge Type: 3-SPAN CONT WLD GDR

Features Intersected: VT 279 OVER VT 67 A

Length: 182' Width: 46.9'

Length: 182' Width: 41.5'

Under Clearance: 14.17'

Surface: Bituminous

Under Clearance: 14.33' Facility Carried: VT 00279 ML

Surface: Bituminous

Maintenance/Ownership: State

Facility Carried: VT 00279 ML


Maintenance/Ownership: State

Stringer/multi-beam or girder - 1973 Structure No. 200110005W02022

Bridge Type: 3-SPAN CONT WLD GDR Features Intersected: VT 279 OVER VT 67 A

STRUCTURE DESCRIPTIONS





Mileage by Functional Class By Sheet

Page Total Mileage: 0.760 mi

1000 4 - Minor Arterial

Mileage by Town By Sheet

0.76 of 0.76

Page Total Mileage: 0.76 mi

DISTRICT

BENNINGTON - V067A0202S

TOWN	Date: 11/15/16	ROUTE VT-67A ETE mileage: 0.102 to 0.862
BENNINGTON	1 of 1 TWN mileage: 0.102 to 0.862	

Road Widths

Traffic Counters

(count) →

Fatal Property Damage Only

■ Injury □ Unknown Crash Type

Historic Projects

Skinny Mix Concrete

Unknown
Retreatment
Resurface
Bituminous Macadam
Resurface
Bituminous Mix
Skinny Mix

Bituminous Concrete
Bituminous Concrete
Bituminous Concrete
Bituminous Concrete
Bituminous Concrete
Bituminous Concrete