## **Route Log and Progress Chart**

**DRAFT** Please Note: Errors and Omissions May Exist.






STRUCTURE DESCRIPTIONS

Bridge <mark>15</mark>: Slab - 1948 Structure No. 200271001505122


Facility Carried: VT 00102 ML


Length: 25' Width: 30.4'






Facility Carried: VI 00102 ML Bridge Type: CONCRETE SLAB Features Intersected: MILL BROOK Surface: Bituminous Maintenance/Ownership: State	
Culvert 15C: Culvert - 1976 Structure No. 300271015C05121 Length: 7' Under Clearance: 5.0' Facility Carried: VT102 Bridge Type: MULTIPLATE PIPE ARCH Features Intersected: BROOK Maintenance: State	







	AADT			
	(count)			
rs	Crash Locations			
	Fatal Property Damage Onl			
	Injury  Unknown Crash Type			
05633	05633-5001 Telephone: 802-828-2600			

		Mileage by Functional Class By	y Sheet	
02	71	5 - Major Collector		7.32
_			Page Total Mileage:	7.324 n
	02	0271	-	

	Mileage by Town By She	eet	
.324	LEMINGTON - V102-0512	7.324 of 7.324	DISTRIC
 24 mi		Page Total Mileage: 7.324 mi	9

<b>ICT</b>	TOWN	Date: 11/15/16	ROUTE
	LEMINGTON	1 of 1 TWN mileage: 0.0 to 7.324	VT-102 ETE mileage: 29.601 to 36.925