

Route Log and Progress Chart

DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.

DISTRICT TOWN ROUTE VT-120 **BERKSHIRE**











Bridge 8: Stringer/multi-beam or girder - 1956 Structure No. 200302000806022
Stringer/multi-beam or girder - 1956 Stringer/multi-beam or girder - 1956
Length: 79'
Length: 79' Width: 29.7'
Facility Carried: VT 00120 ML Bridge Type: ROLLED BEAM Features Intersected: PIKE RIVER
Features Intersected: PIKE RIVER
Surface: Bituminous
Maintenance/Ownership: State

STRUCTURE DESCRIPTIONS










Road Widths ← (ft) →	AADT ← (count)
raffic Counters (counter ID)	Crash Locations ■ Fatal □ Property Dam □ Injury □ Unknown Cra

	AADI	L
	← (count)	
Fata	Crash Locations Property Damage Only Unknown Crash Type	



Mileage by Functional Class By Sheet 0302 5 - Major Collector Page Total Mileage: 0.318 mi

Mileage by Town By Sheet 0.318 of 0.318 BERKSHIRE - V120-0602 Page Total Mileage: 0.318 mi

DISTRICT

TOWN ROUTE Date: 11/15/16 VT-120 1 of 1 **BERKSHIRE** TWN mileage: 10.236 to 10.554 0.0 to 0.318