## **DISTRICT TOWN ROUTE DRAFT Route Log and Progress Chart** Please Note: Errors and Omissions May Exist. WILLIAMSTOWN, BERLIN, I-89 Contact the VTrans Mapping Section with questions or concerns. **MONTPELIER** NORTHEIELD Base Map BERLIN MIDDLESEX WILLIAMSTOWN SOUTH 1 in = 0.7 milesStick Diagram STRUCTURE DESCRIPTIONS Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, +-+-++ Railroad Crossings Bridge 36S: Stringer/multi-beam or girder - 1970 Primary Structures Structure No. 200089036S12032 Length: 174' Secondary Structures Width: 39.6' Divided State Highway Under Clearance: 14.25' State Highway Facility Carried: I 89 ML Structure Type: 2 SP CONT ROLLED BM Divided Town Highway Features Intersected: I 89 OVER VT 63 — Town Highway Surface: Bituminous Streams (Hydraulic Structure) Maintenance/Ownership: State Town Boundary - - - Village/UC Boundaries Bridge 36-3: --- District Boundaries Culvert - 1970 o - o - State/Town Highway Change Structure No. 30008936-312031 --- Divided Highway Limits Length: 12' Under Clearance: 3.0' ---- Ghost Section Boundary Facility Carried: I89 ----- Federal Urban Area Limits Structure Type: RC BOX Features Intersected: BERLIN POND OUTLET Scale: 1 INCH = 2,000 FEET Maintenance: State 52 | | | | | Culvert - 1970 Structure No. 30008936-412031 Travellane Length: 9' Roadway Under Clearance: 7.0' **Road Widths** Lane Count Facility Carried: I89 5" Crushed Stone Base Cours Structure Type: RC BOX Features Intersected: WATER MAIN SLEEVE Subbase Maintenance: State Curves Stringer/multi-beam or girder - 1970 Structure No. 200089037S12032 Length: 122' Width: 38.0' Grades Under Clearance: 14.25' Facility Carried: I 89 ML Structure Type: WELDED PLATE GIRDER **Guardrails** Features Intersected: I 89 OVER TH NO 40 Surface: Bituminous Maintenance/Ownership: State **Rumblestrips** Stringer/multi-beam or girder - 1970 Structure No. 200089038S12032 Length: 174' Width: 47.0' Under Clearance: 15.08' Facility Carried: I 89 ML Structure Type: 2 SP CONT ROLLED BM Features Intersected: I 89 OVER VT 62 Surface: Bituminous 2006: IM SURF(2) 1998: IM 089-1(16) Maintenance/Ownership: State Historic Projects Bridge 39: Stringer/multi-beam or girder - 1970 1987: IR 089-1(6) Structure No. 2012030D3912031 1982: IR 089-2(3) Length: 230' Facility Carried: TR 18 Structure Type: 2SP CONT WLD PLT GIR Features Intersected: I 89 UNDER TH NO 18 Stringer/multi-beam or girder - 1970 Structure No. 200089040S12032 Length: 449' Width: 39.0' District 6 - DMF Maintenance Middlesex Garage District 5 - DMF Maintenance Middlesex Garage **Maintenance Garage** Under Clearance: 64.0' Facility Carried: I 89 ML Structure Type: 3 SP WLD PLT GIRDER Features Intersected: I 89 OVER VT 12 Speed Zone Maintenance/Ownership: State **Functional Class** Stringer/multi-beam or girder - 1960 Structure No. 200089041S12112 Length: 153' ( National Highway System Width: 42.0' Under Clearance: 14.17' Facility Carried: I 89 ML Structure Type: 3 SPAN ROLLED BEAM **Limited Access Highway** Features Intersected: I 89 OVER MONT. S.H. Surface: Bituminous Maintenance/Ownership: State Interstate Or Divided Highway **Customer Service Level** Bridge 42S: Stringer/multi-beam or girder - 1960 Structure No. 200089042S12112 **Traffic Counters** Length: 955' Width: 31.5' Under Clearance: 22.0' Facility Carried: I 89 ML 7337 8194 7058 9597 Structure Type: 13 SPAN ROLLED BEAM Features Intersected: I 89 OVER US2 WR WCRR 9782 8347 10583 10583 8218 11939 9410 12796 Surface: Bituminous Maintenance/Ownership: State **AADT** Bridge 42-1: 2017 Culvert - 1960 Structure No. 30008942-112111 Length: 7' Under Clearance: 7.58' Facility Carried: I89 Structure Type: CGMPP (Incomplete) 2021 Features Intersected: BROOK Maintenance: State **Crash Locations** 2019 -ф-

2017