



DISTRICT	TOWN	ROUTE
9	BROWNINGTON, COVENTRY, IRASBURG, DERBY	I-91



Road Widths	Travellane	Roadway	Lane Count	Base	Subbase

Curves	Grades
	+4.5, +4, -4, +5

Guardrails

Rumblestrips

Historic Projects
2013: IM 091-3(45), 2013: IM BPNT(11), 2011: IM IR 091-3(6), 2010: IM 091-3(46), 1988: IR 091-3(3), 1972: SMP 181-3(20) STAGE 3, 1977: 191-3(37), 2011: IM 091-3(47), 1975: 191-3(34) STAGE 3, 1972: 191-3(6), 1971: 191-3(21)

Maintenance Garage
District 9 - DMF Maintenance Derby Garage

Speed Zone

Functional Class
1

National Highway System
NHS - Interstate

Limited Access Highway
Full

Customer Service Level
Interstate Or Divided Highway

Traffic Counters

AAADT
2020: 3024, 1812, 2208; 2019: 4032, 2416, 2944; 2018: ; 2017: ; 2016:

Crash Locations
(Incomplete) 2021: ; 2020: ; 2019: ; 2018: ; 2017:

STRUCTURE DESCRIPTIONS

Bridge 107S:
Stringer/multi-beam or girder - 1971
Structure No. 200091107S10112
Length: 447'
Width: 39.4'
Under Clearance: 26.08'
Facility Carried: 191 ML
Structure Type: SSP CONT W GIR / RBM
Features Intersected: TH38 + CRLRR + BARTON RV
Surface: Bituminous
Maintenance/Ownership: State

Bridge 107-1:
Culvert - 1972
Structure No. 300091107110111
Length: 6'
Under Clearance: 6.0'
Facility Carried: I91
Structure Type: ACCGMPP
Features Intersected: SWAMP DRAIN
Maintenance: State

Bridge 107-3:
Culvert - 1972
Structure No. 300091107310031
Length: 8'
Under Clearance: 8.5'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: TROUT BROOK
Maintenance: State

Bridge 108S:
Frame - 1971
Structure No. 201005D08S10051
Length: 124'
Facility Carried: TR 03
Structure Type: STEEL RIGID FRAME
Features Intersected: 191 UNDER TH NO 3
Maintenance: State

Bridge 1081S:
Culvert - 1972
Structure No. 300091H81S10051
Length: 7'
Under Clearance: 5.0'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: BROOK
Maintenance: State

Bridge 1083S:
Culvert - 1972
Structure No. 300091H83S10051
Length: 13'
Under Clearance: 9.0'
Facility Carried: I91
Structure Type: CGMPPA W CONC INVERT
Features Intersected: DAY BROOK
Maintenance: State

Bridge 1088S:
Culvert - 1997
Structure No. 300091H88S10071
Length: 15'
Facility Carried: I91
Structure Type: CGMPPA
Features Intersected: COBB BROOK
Maintenance: State

Bridge 109:
Stringer/multi-beam or girder - 1970
Structure No. 201343000110072
Length: 375'
Facility Carried: VT 00191 SPUR
Structure Type: 3 SP CONT WLD GIRDER
Features Intersected: 191 UNDER VT 191

Historic Projects <ul style="list-style-type: none"> Unknown Retreatment Resurface Bituminous Mix Skinny Mix Bituminous Seal 	Functional Class <ul style="list-style-type: none"> 1 - Interstate System 2 - Other 3 - Principal Arterial 4 - Minor Arterial 5 - Major Collector 6 - Minor Collector 	Curves <ul style="list-style-type: none"> Left (degrees) Right 	Grades <ul style="list-style-type: none"> grade up grade down 	Traffic Counters <ul style="list-style-type: none"> Continuous (CTC) Weigh-In-Motion (WIM) Short-Term, Scheduled Short-Term, Unscheduled 	Crash Locations <ul style="list-style-type: none"> High Crash Locations (HCL's) HCL No. 1-100 (1-10) 101-200 (11-20) 201-300 (21-30) 301-400 (31-40) 401-800 (41-113) 	Mileage by Functional Class By Sheet 91-3 1 - Interstate 9.000	Mileage by Town By Sheet ETE - I091-0000S 9.0 of 177.432	DISTRICT 9	TOWN BROWNINGTON, COVENTRY, IRASBURG, DERBY	Date: 11/22/21	ROUTE I-91 ETE mileage: 162.0 to 171.0
--	---	--	---	--	---	--	--	----------------------	---	-----------------------	---