

Retreatment Bituminous Macadam

Resurface


Route Log and Progress Chart

Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.


DRAFT

DISTRICT TOWN ROUTE SHARON, HARTFORD I-89

Page Total Mileage: 9.0 mi







Bridge <mark>9-4</mark>: Culvert - 1967 Structure No. 30008909-414081 Length: 6' Under Clearance: 7.0' Facility Carried: I89 Structure Type: CGMPP Features Intersected: BROOK Maintenance: State

Stringer/multi-beam or girder - 1967 Structure No. 2014080D1014081 Facility Carried: TR 36 Structure Type: 2 SP CONT WELDED GIR Features Intersected: I 89 UNDER TH NO 36

Bridge 10-1: Culvert - 1967 Structure No. 30008910-114081 Length: 10' Under Clearance: 11.0' Facility Carried: I89 Structure Type: CGMPP Features Intersected: BROOK Maintenance: State

Stringer/multi-beam or girder - 1967 Structure No. 200089011N14082 Length: 1059' Width: 32.0' Under Clearance: 21.42' Facility Carried: I 89 ML Structure Type: 6 SP CONT GIRDERS Features Intersected: I 89 OVER WR+NEC RR + 14 Surface: Bituminous Maintenance/Ownership: State

Bridge 11-1N: Culvert - 1968 Structure No. 300089111N14081 Length: 10' Under Clearance: 8.0' Facility Carried: 189 Structure Type: RC BOX Features Intersected: PODUNK BROOK Maintenance: State

Culvert - 1968 Structure No. 300089112N14081 Length: 9' Under Clearance: 9.0' Facility Carried: I89 Structure Type: CGMPP Features Intersected: TIGERTOWN BROOK Maintenance: State

Frame - 1968 Structure No. 200089012N14082 Length: 21' Under Clearance: 14.08' Facility Carried: I 89 ML Structure Type: RC BOX Features Intersected: I 89 OVER TH NO 13 Maintenance/Ownership: State

ROUTE

ETE mileage:

0.0 to 9.0

1 of 15

TWN mileage:

0.0 to 9.0

SHARON, HARTFORD

4 - Minor Arterial

Freeways and

■ Injury □ Unknown Crash Type

High Crash Locations (HCL's)

Traffic Counters