

## **Route Log and Progress Chart**

	Vermont Agency of Transportation			J	Contact t	Please Note: Errors he VTrans Mapping Section w	and Omissions May Exist. ith questions or concerns.	1
Base Map	WILMINGTON			•		MARLBORO	3	
Stick Diagram	01 				1880 HUGHES RD (TH-31) TH 24 (TH-24)			
0 Travellane Road Widths Lane Count Base Subbase	•			24 24 24 2	2		3)	
Curves								
Grades								
Guardrails								
Rumblestrips								
Historic Projects								
Maintenance Garage								
Speed Zone								
Functional Class				6				
National Highway System								
Limited Access Highway								
Customer Service Level								
Traffic Counters					X036	XYBQ X363		
2022 2021 <b>AADT</b> 2020 2019 2018								
(Incomplete) 2023								
2022								
Crash Locations 2021 2020								
2019			<b></b> -			ational Class Brocks - 1		
<ul> <li>Unknown</li> <li>Bituminous Concre</li> <li>Bituminous Macada</li> <li>Resurface</li> <li>Bituminous Mix</li> <li>Skinny Mix</li> <li>Bituminous Seal</li> </ul>	ete Surface Treated am Gravel Plant Mix ete Reclaimed Base and Bituminous Concrete	Arterial 5 - Major Arterial Collector 4 - Minor Arterial 6 - Minor Arterial Collector 5 - Major Collector 6 - Minor Arterial Collector Figure Rig Collector Rig Collector Rig Collector Rig	t grade up	/IM) Fatal Property Damage On Injury Unknown Crash Type	Nly 0526 6 - Minor Collector	ctional Class By Sheet	Mileage           3.370         MARLBORO - \$05261311	by Town By Sheet

DISTRICT

DRAFT



Page Total Mileage: 3.37 mi