Route Log and Progress Chart

DRAFT

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Section with questions or concerns.

DISTRICT	TOWN	ROUTE
4	HARTFORD	US-5



5



STRUCTURE DESCRIPTIONS

Bridge 68:
Culvert - 2018
Structure No. 300113006814081
Length: 170'
Facility Carried: US5
Structure Type: CGMPP
Features Intersected: BROOK
Inspection Date: 11/2020
Maintenance: State

Bridge 70:
Stringer/multi-beam or girder
Structure No. 200089006S14082
Length: 187'
Facility Carried: I 89
Structure Type: 3 SPAN ROLLED BEAM
Maintenance/Ownership: State

Bridge 70-1:
Stringer/multi-beam or girder
Structure No. 200089006N14082
Length: 192'
Facility Carried: I 89
Structure Type: 3 SPAN ROLLED BEAM
Maintenance/Ownership: State

Bridge 71:
Stringer/multi-beam or girder
Structure No. 200091043S14082
Length: 136'
Facility Carried: I 91
Structure Type: WELDED GIRDER
Maintenance/Ownership: State

Bridge 71A:
Stringer/multi-beam or girder
Structure No. 200091043N14082
Length: 136'
Facility Carried: I 91
Structure Type: WELDED GIRDER
Maintenance/Ownership: State

Bridge 73:
Stringer/multi-beam or girder - 1968
Structure No. 200113007314082
Length: 979'
Width: 57.0'
Under Clearance: 23.08'
Facility Carried: US 05
Structure Type: 6 SP CONT WLD GIRDER
Features Intersected: US 5 OVER WHI R + NECRR
Surface: Bituminous
Inspection Date: 82/23
Maintenance/Ownership: State

Bridge 75:
Slab - 1977
Structure No. 300113007514081
Length: 22'
Width: 33.6'
Under Clearance: 4.0'
Facility Carried: US5
Structure Type: CONCRETE SLAB
Features Intersected: DOTHAN BROOK
Surface: Bituminous
Inspection Date: 11/2020
Maintenance: State

Bridge 75A:
Stringer/multi-beam or girder
Structure No. 200091047N14082
Length: 197'
Facility Carried: I 91
Structure Type: 3 SP CONT WLD PL GIR
Maintenance/Ownership: State

Bridge 75B:
Stringer/multi-beam or girder
Structure No. 200091047S14082
Length: 197'
Facility Carried: I 91
Structure Type: 3 SP CONT WLD PL GIR
Maintenance/Ownership: State

Bridge 77:
Culvert - 1931
Structure No. 300113007714081
Length: 8'
Under Clearance: 6.0'
Facility Carried: US5
Structure Type: RC BOX
Features Intersected: BROOK
Inspection Date: 12/2020
Maintenance: State

Historic Projects: Unknown; Retreatment; Resurface; Bituminous Mix; Skinny Mix; Bituminous Seal; Bituminous Concrete; Bituminous Macadam; Cold Plane and Bituminous Concrete; Concrete; Gravel; Surface Treated Gravel; Plant Mix; Reclaimed Base and Bituminous Concrete

Functional Class: 1 - Interstate System; 2 - Other Freeways and Expressways; 3 - Principal Arterial; 4 - Minor Arterial; 5 - Major Collector; 6 - Minor Collector

Speed Zones: 25, 30, 35, 40, 45, 50, 55, 60, 65

Curves: Left (degrees); Right

Grades: grade up (percent); grade down

Road Widths (ft)

Traffic Counters: Continuous (CTC); Weigh-In-Motion (WIM); Short-Term, Scheduled; Short-Term, Unscheduled (counter ID); AADT (AADT)

Crash Locations: Fatal; Injury; Property Damage Only; Unknown Crash Type

High Crash Locations (HCL's) Sections (& Intersections)
HCL No.
1 - 100 (1 - 10)
101 - 200 (11 - 20)
201 - 300 (21 - 30)
301 - 400 (31 - 40)
401 - 800 (41 - 113)

Mileage by Functional Class By Sheet

020-2	4 - Minor Arterial	0.560
0113	5 - Major Collector	6.990

Page Total Mileage: 7.550 mi

Mileage by Town By Sheet

HARTFORD - U005-1408	7.55 of 7.55

Page Total Mileage: 7.55 mi

DISTRICT	TOWN	Date: 11/21/25	ROUTE
4	HARTFORD	1 of 1 TWN mileage: 0.0 to 7.55	US-5 ETE mileage: 70.842 to 78.392

For More Information Contact - Vermont Agency of Transportation, Policy, Planning and Intermodal Development Division - Mapping Section, 219 North Main Street, Barre, VT 05641 Telephone: 802-828-2600.