Trans Working to Get You There Vermont Agency of Transportation	Route Log and Progress Chart	DRAFT  Please Note: Errors and Omissions May Exist.  Contact the VTrans Mapping Section with questions or concerns.	DISTRICT TOWN ROUTE  1 GLASTENBURY US-7	
				7
Base Map	SHAFTSBURY		ARLINGTON	
z >	GLASTENBURY		SÜNDERLAND	
1 in = 1,000 feet			CONSENSIVE	
Stick Diagram				
Town Center Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, Approaches Primary Structures  Secondary Structures  Divided State Highway State Highway Divided Town Highway Town Highway Town Highway Town Boundary Town Boundary District Boundaries	SHAFT SAULT			Bridge 19: Frame - 1978 Structure No. 200019001902042 Length: 28' Height: 100.0' Width: 46.0' Under Clearance: 14.0' Weight Limit: 0 Facility Carried: US 07 ML Structure Type: RC BOX Features Intersected: US 7 OVER TH NO 1
O - O - State/Town Highway Change O - O - State/Town Highway Limits O - O - State/Town Highway Limits O - O - State/Town Highway Change O - O - State/Town Highway Limits O - O - O - State/Town Highway Limits O - O - O - State/Town Highway Limits O - O - O - State/Town Highway Limits O - O - State/Town Highway Limits O - O - O - State/Town Highway Limits O - O - O - State/Town Highway Limits O - O - O - State/Town Highway Limits O - O - O - O - O - O - O - O - O - O -	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			Inspection Date: 5/2023 Maintenance/Ownership: State  Bridge 19-2: Culvert - 1978 Structure No. 30001919-202041 Length: 22' Under Clearance: 8.0' Weight Limit: 0 Facility Carried: US7
Road Widths  Travellane Roadway Lane Count Base Subbase  Travellane  Roadway  46  47  47  2 - 2 1/2" Plant Mix Base Course  24" Crushed Gravel	3  Two 2 1/2" Plant Mix Base Courses  24" Crushed Gravel			Structure Type: RC BOX Features Intersected: FAYVILLE BROOK Inspection Date: 12/2020 Maintenance: State  Bridge 19-4: Culvert - 1979 Structure No. 30001919-402041 Length: 7' Under Clearance: 7.0'
Curves 4.9	5.1			Weight Limit: 0 Facility Carried: US7 Structure Type: CGMPP
Grades				Features Intersected: BROOK Inspection Date: 12/2020 Maintenance: State
Guardrails				Maintenance. State
Rumblestrips				
Historic Projects  2013: NH SURF(29) 2000: NH 9812(1)S	2013: NH SURF(29)  2000: NH 9812(1)S			
1978: RF 019-1(8) C/2	1978: RF 019-1(8) C/2 1978: RF 019-1(8) C/3			
Maintenance Garage  District 1 - DMF Maintenance Bennington Garage	District 1 - DMF Maintenance Bennington Garage			
Speed Zone	FPED LIMIT 55			
Functional Class 3	3			
National Highway System NHS - Other NHS Routes	NHS - Other NHS Routes			
Limited Access Highway	Full			
Customer Service Level Interstate Or Divided Highway	Interstate Or Divided Highway			
Traffic Counters				
7018	6716			
2022 2021 7536 2020 2019 2018 7853 7800	7536 6651 7853 7800			
(Incomplete) 2023				

Mileage by Town By Sheet

1.784 of 1.784

1.784 GLASTENBURY - U007-0204

Mileage by Functional Class By Sheet

Crash Locations 2021

Historic Projects

**Functional Class** 

**Curves Grades** 

Traffic Counters

**Crash Locations**