



DISTRICT	TOWN	ROUTE
4	CHELSEA	VT-113



Travel Lane	Roadway	Lane Count	Base	Subbase
27	27	27	27.5	28
28	28	28	28.5	29
29	29	29	29.5	30
30	30	30	30.5	31
31	31	31	31.5	32
32	32	32	32.5	33
33	33	33	33.5	34
34	34	34	34.5	35
35	35	35	35.5	36
36	36	36	36.5	37
37	37	37	37.5	38
38	38	38	38.5	39
39	39	39	39.5	40
40	40	40	40.5	41
41	41	41	41.5	42
42	42	42	42.5	43
43	43	43	43.5	44
44	44	44	44.5	45
45	45	45	45.5	46
46	46	46	46.5	47
47	47	47	47.5	48
48	48	48	48.5	49
49	49	49	49.5	50
50	50	50	50.5	51
51	51	51	51.5	52
52	52	52	52.5	53
53	53	53	53.5	54
54	54	54	54.5	55
55	55	55	55.5	56
56	56	56	56.5	57
57	57	57	57.5	58
58	58	58	58.5	59
59	59	59	59.5	60
60	60	60	60.5	61
61	61	61	61.5	62
62	62	62	62.5	63
63	63	63	63.5	64
64	64	64	64.5	65
65	65	65	65.5	66
66	66	66	66.5	67
67	67	67	67.5	68
68	68	68	68.5	69
69	69	69	69.5	70
70	70	70	70.5	71
71	71	71	71.5	72
72	72	72	72.5	73
73	73	73	73.5	74
74	74	74	74.5	75
75	75	75	75.5	76
76	76	76	76.5	77
77	77	77	77.5	78
78	78	78	78.5	79
79	79	79	79.5	80
80	80	80	80.5	81
81	81	81	81.5	82
82	82	82	82.5	83
83	83	83	83.5	84
84	84	84	84.5	85
85	85	85	85.5	86
86	86	86	86.5	87
87	87	87	87.5	88
88	88	88	88.5	89
89	89	89	89.5	90
90	90	90	90.5	91
91	91	91	91.5	92
92	92	92	92.5	93
93	93	93	93.5	94
94	94	94	94.5	95
95	95	95	95.5	96
96	96	96	96.5	97
97	97	97	97.5	98
98	98	98	98.5	99
99	99	99	99.5	100

Curves	Grades
2.3, 18.4, 7.2, 4.6, 4.6, 11.5, 7.6, 12.7, 14.3, 7.2, 5.7, 9.5, 11.5, 7.2, 2.9, 8.2	+7.0A, +6.6, +4.8A, +4.8A, +5.8, +4.8A, +3.8A, +4.2A, +5.3A, +6.8A

Guardrails
None

Rumblestrips
None

Historic Projects
2010: STP 2331(1)
1992: STP 9311(1)S
1988: Unknown
1988: HMA 2949
1985: Unknown
1983: HMA 2407
1978: Unknown
1973: -
1949: S 17627
1953: S 17665

Maintenance Garage
District 4 - DMF Maintenance Thetford Garage

Speed Zone
30, 40

Functional Class
5 - Major Collector

National Highway System
None

Limited Access Highway
None

Customer Service Level
Local Connector

Traffic Counters
N133

ADT	2022	2021	2020	2019	2018
	725	719	635	750	750

Crash Locations	2022	2021	2020	2019
(Incomplete)				

## STRUCTURE DESCRIPTIONS

<p><b>Bridge 1:</b> Frame - 1941 Structure No. 300180000109041 Length: 18' Under Clearance: 10.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: CONCRETE RIGID FRAME Features Intersected: JAIL BROOK Inspection Date: 12/2018 Maintenance: State</p>
<p><b>Bridge 2:</b> Slab - 1949 Structure No. 300180000209041 Length: 18' Width: 30.0' Under Clearance: 12.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: CONCRETE SLAB Features Intersected: JAIL BROOK Surface: Bituminous Inspection Date: 12/2018 Maintenance: State</p>
<p><b>Bridge 3:</b> Culvert - 1929 Structure No. 300180000309041 Length: 19' Width: 31.0' Under Clearance: 7.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: RC BOX Features Intersected: JAIL BROOK Inspection Date: 12/2018 Maintenance: State</p>
<p><b>Bridge 4:</b> Slab - 1949 Structure No. 300180000409041 Length: 20' Width: 30.0' Under Clearance: 8.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: CONCRETE SLAB Features Intersected: JAIL BROOK Surface: Bituminous Inspection Date: 12/2018 Maintenance: State</p>
<p><b>Bridge 5:</b> Slab - 1949 Structure No. 300180000509041 Length: 15' Width: 30.0' Under Clearance: 8.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: CONCRETE SLAB Features Intersected: JAIL BROOK Surface: Bituminous Inspection Date: 12/2018 Maintenance: State</p>
<p><b>Bridge 6:</b> Slab - 1949 Structure No. 300180000609041 Length: 22' Width: 30.0' Under Clearance: 9.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: CONCRETE SLAB Features Intersected: JAIL BROOK Surface: Bituminous Inspection Date: 12/2018 Maintenance: State</p>
<p><b>Bridge 7:</b> Slab - 1949 Structure No. 300180000709041 Length: 16' Width: 30.0' Under Clearance: 10.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: CONCRETE SLAB Features Intersected: JAIL BROOK Surface: Bituminous Inspection Date: 12/2018 Maintenance: State</p>
<p><b>Bridge 8:</b> Slab - 1949 Structure No. 300180000809041 Length: 12' Width: 31.0' Under Clearance: 10.0' Weight Limit: 0 Facility Carried: VT113 Structure Type: CONCRETE SLAB Features Intersected: JAIL BROOK Surface: Bituminous Inspection Date: 12/2018 Maintenance: State</p>

Historic Projects	Functional Class	Curves	Grades	Traffic Counters	Crash Locations	Mileage by Functional Class By Sheet	Mileage by Town By Sheet	DISTRICT	TOWN	Date: 09/23/23	ROUTE
<ul style="list-style-type: none"> <li>Unknown</li> <li>Retreatment</li> <li>Resurface</li> <li>Bituminous Mix</li> <li>Skippy Mix</li> <li>Bituminous Seal</li> </ul>	<ul style="list-style-type: none"> <li>1 - Interstate System</li> <li>2 - Other Freeways and Expressways</li> <li>3 - Principal Arterial</li> <li>4 - Minor Arterial</li> <li>5 - Major Collector</li> <li>6 - Minor Collector</li> </ul>	<ul style="list-style-type: none"> <li>Left</li> <li>Right</li> </ul>	<ul style="list-style-type: none"> <li>Special grade up</li> <li>Special grade down</li> </ul>	<ul style="list-style-type: none"> <li>Continuous (CTC)</li> <li>Weight-In-Motion (WIM)</li> <li>Short-Term, Scheduled</li> <li>Short-Term, Unscheduled</li> </ul>	<ul style="list-style-type: none"> <li>Fatal</li> <li>Injury</li> <li>Property Damage Only</li> <li>Unknown Crash Type</li> </ul>	0180 5 - Major Collector 3.440	CHELSEA - V113-0904 3.44 of 3.44	4	CHELSEA	1 of 1 TWN mileage: 0.0 to 3.44	VT-113 ETE mileage: 0.0 to 3.44
Indicated plans available - <a href="http://vtransmap01.aot.state.vt.us/p/dcr/DWebstore/">http://vtransmap01.aot.state.vt.us/p/dcr/DWebstore/</a>						Page Total Mileage: 3.440 mi		Page Total Mileage: 3.44 mi			