


NOTE - The attention of the contractor is called to the spring left of Sta. 77+00. He shall take proper precautions during construction to avoid damage to the spring, as it is necessary that the flow from the spring be maintained during construction. The contractor is held liable for any damage done to the spring, from the beginning of construction to the satisfactory completion of the contract.

Rev Curve
A 14.29'
D 0.35'
R 11453.2
T 160.0
L 380.0
E 1.19

Survey Point 77+00.3
A 11.13
L 26.25
E 2.5

Parcel	Instrument	Date	Grantor	Grantee	Recorded Book	Page	Recorded Date	Remarks
A	a.c.o.	2-6-36	Bellows Falls Hydro-Electric Corp.	S/1944	75	294-296	2-14-36	



Sta 70+00 - Sta 79+00
12' Sub-base of Gravel

Station	Elevation
65	344.8
66	344.1
67	343.2
68	343.0
69	342.8
70	342.6
71	342.3
72	342.47
73	342.39
74	342.3
75	342.27
76	342.25
77	342.2
78	342.19
79	342.1
80	342.0
81	341.9
82	341.8
83	341.7
84	341.6
85	341.5
86	341.4
87	341.3
88	341.2
89	341.1
90	341.0
91	340.9
92	340.8
93	340.7
94	340.6
95	340.5
96	340.4
97	340.3
98	340.2
99	340.1
100	340.0
101	339.9
102	339.8
103	339.7
104	339.6
105	339.5
106	339.4
107	339.3
108	339.2
109	339.1
110	339.0
111	338.9
112	338.8
113	338.7
114	338.6
115	338.5
116	338.4
117	338.3
118	338.2
119	338.1
120	338.0
121	337.9
122	337.8
123	337.7
124	337.6
125	337.5
126	337.4
127	337.3
128	337.2
129	337.1
130	337.0
131	336.9
132	336.8
133	336.7
134	336.6
135	336.5
136	336.4
137	336.3
138	336.2
139	336.1
140	336.0
141	335.9
142	335.8
143	335.7
144	335.6
145	335.5
146	335.4
147	335.3
148	335.2
149	335.1
150	335.0

B.M. #15 SPIKE IN ROOT OF 12" BUTTERNUT 50 FT. TO RT. OF STATION 78+18. ELEV 355.45