

BORING LOG		Boring No.: B-4B																									
Project Name		Page No.: 1 of 1																									
Route 125 Bridge RS 0174 (8) Middlebury, VT		File No.: 750-04.1																									
Checked By: JEL																											
<p><b>Geodesign Incorporated</b> Geotechnical Engineers/Environmental Consultants/Construction Engineers P.O. Box 688 Windsor, VT 05689 Phone: 802-474-8223/Fax: 802-474-5943</p> <p><b>H &amp; W Sells Engineering, Inc.</b> 1233 Shelburne Rd., Suite 300 St. Burlington, VT 05408 Phone: 802-652-5149</p>																											
<p>Boring Company: <b>H &amp; W Sells Engineering, Inc.</b> Personnel: <b>Myron Domingue</b> Contractor: <b>James Goodrich</b> Date Started: <b>July 8, 2003</b> Date Finished: <b>July 8, 2003</b> N. Coordinate: <b>532.8</b> E. Coordinate: <b>532.7</b> Ground Surface Elevation (feet): <b>532.8</b> Station: <b>14182.00</b> Offset: <b>22 ft RT</b></p>																											
<table border="1"> <thead> <tr> <th colspan="2">Sample Information</th> <th colspan="2">Sample Description</th> </tr> <tr> <th>Depth (ft)</th> <th>Core Length (ft)</th> <th>Strata Description</th> <th>Sample Description</th> </tr> </thead> <tbody> <tr> <td>0 - 0.5</td> <td>0.5</td> <td>SHIMMERS CONCRETE</td> <td></td> </tr> <tr> <td>0.5 - 4.5</td> <td>4.0</td> <td>Silty SAND and GRAVEL</td> <td></td> </tr> <tr> <td>4.5 - 7.2</td> <td>2.7</td> <td>Silty SAND and GRAVEL (with Cobbles and Boulders)</td> <td>S1: Very dense / Refusal. Top 6": Gray fine SAND and Silt. Bottom 7": Brown, layered fine to medium SAND, little Silt, with roots and root fibers. Oxidized orange to dark red. Pieces of fractured gravel/cobbles in spoon tip.</td> </tr> <tr> <td>7.2 - 50.0</td> <td>42.8</td> <td>Bottom of Exploration at 7.2 ft</td> <td></td> </tr> </tbody> </table>				Sample Information		Sample Description		Depth (ft)	Core Length (ft)	Strata Description	Sample Description	0 - 0.5	0.5	SHIMMERS CONCRETE		0.5 - 4.5	4.0	Silty SAND and GRAVEL		4.5 - 7.2	2.7	Silty SAND and GRAVEL (with Cobbles and Boulders)	S1: Very dense / Refusal. Top 6": Gray fine SAND and Silt. Bottom 7": Brown, layered fine to medium SAND, little Silt, with roots and root fibers. Oxidized orange to dark red. Pieces of fractured gravel/cobbles in spoon tip.	7.2 - 50.0	42.8	Bottom of Exploration at 7.2 ft	
Sample Information		Sample Description																									
Depth (ft)	Core Length (ft)	Strata Description	Sample Description																								
0 - 0.5	0.5	SHIMMERS CONCRETE																									
0.5 - 4.5	4.0	Silty SAND and GRAVEL																									
4.5 - 7.2	2.7	Silty SAND and GRAVEL (with Cobbles and Boulders)	S1: Very dense / Refusal. Top 6": Gray fine SAND and Silt. Bottom 7": Brown, layered fine to medium SAND, little Silt, with roots and root fibers. Oxidized orange to dark red. Pieces of fractured gravel/cobbles in spoon tip.																								
7.2 - 50.0	42.8	Bottom of Exploration at 7.2 ft																									
<p>Notes: 1) Ground surface elevation established in the field by Geodesign using a hand level. 2) 4.25" O.D. solid stem auger used to advance borings. Further resistance observed between 4.5" to 5" deep and 6" to 7.2" through possible cobbles and small boulders. 3) Solid stem auger refused at 7.2" on possible large boulder or bedrock.</p>																											
<p>Scale: 1" = 10' Vertical, 1" = 10' Horizontal</p>																											
<p>Boring No.: B-4B</p>																											

BORING LOG		Boring No.: B-5																					
Project Name		Page No.: 1 of 2																					
Route 125 Bridge RS 0174 (8) Middlebury, VT		File No.: 750-04.1																					
Checked By: JEL																							
<p><b>Geodesign Incorporated</b> Geotechnical Engineers/Environmental Consultants/Construction Engineers P.O. Box 688 Windsor, VT 05689 Phone: 802-474-8223/Fax: 802-474-5943</p> <p><b>H &amp; W Sells Engineering, Inc.</b> 1233 Shelburne Rd., Suite 300 St. Burlington, VT 05408 Phone: 802-652-5149</p>																							
<p>Boring Company: <b>H &amp; W Sells Engineering, Inc.</b> Personnel: <b>Myron Domingue</b> Contractor: <b>James Goodrich</b> Date Started: <b>July 8, 2003</b> Date Finished: <b>July 11, 2003</b> N. Coordinate: <b>532.7</b> E. Coordinate: <b>532.7</b> Ground Surface Elevation (feet): <b>532.7</b> Station: <b>14190.00</b> Offset: <b>27 ft LT</b></p>																							
<table border="1"> <thead> <tr> <th colspan="2">Sample Information</th> <th colspan="2">Sample Description</th> </tr> <tr> <th>Depth (ft)</th> <th>Core Length (ft)</th> <th>Strata Description</th> <th>Sample Description</th> </tr> </thead> <tbody> <tr> <td>0 - 1.5</td> <td>1.5</td> <td>TOPSOIL</td> <td>S1: Medium dense, dark brown, fine SAND and SILT, trace gravel, with roots and root fibers, moist.</td> </tr> <tr> <td>1.5 - 4.5</td> <td>3.0</td> <td>Silty SAND (with Cobbles and Boulders)</td> <td>S2: Refusal. Similar to S1, except fine to medium SAND, with organic litter.</td> </tr> <tr> <td>4.5 - 52.2</td> <td>47.7</td> <td>BEDROCK (Quartzite)</td> <td>C1: Very hard, light to dark gray, slightly weathered orange-red along fracture surfaces, closely jointed, poor quality QUARTZITE (ROD=38%). Fractures typically &lt;15 and 45 degrees from horizontal. C2: Similar rock type to above (ROD=25%). C3: Similar rock type to above. C4: Similar rock type to above (ROD=25%). Fractures typically &lt;10 and &gt;70 degrees from horizontal. C5: Similar rock type to above, except close to very closely jointed (ROD=32%). Two 3/4" thick dark gray to black SLATE beds noted near bottom of run. C6: Similar rock type to above, except closely jointed, very poor quality (ROD=18%). One 0.5" thick black SLATE bed noted. C7: Similar rock type to above, except close to very closely jointed (ROD=85%). Fractures typically &lt;10 and 70-85 degrees from</td> </tr> </tbody> </table>				Sample Information		Sample Description		Depth (ft)	Core Length (ft)	Strata Description	Sample Description	0 - 1.5	1.5	TOPSOIL	S1: Medium dense, dark brown, fine SAND and SILT, trace gravel, with roots and root fibers, moist.	1.5 - 4.5	3.0	Silty SAND (with Cobbles and Boulders)	S2: Refusal. Similar to S1, except fine to medium SAND, with organic litter.	4.5 - 52.2	47.7	BEDROCK (Quartzite)	C1: Very hard, light to dark gray, slightly weathered orange-red along fracture surfaces, closely jointed, poor quality QUARTZITE (ROD=38%). Fractures typically <15 and 45 degrees from horizontal. C2: Similar rock type to above (ROD=25%). C3: Similar rock type to above. C4: Similar rock type to above (ROD=25%). Fractures typically <10 and >70 degrees from horizontal. C5: Similar rock type to above, except close to very closely jointed (ROD=32%). Two 3/4" thick dark gray to black SLATE beds noted near bottom of run. C6: Similar rock type to above, except closely jointed, very poor quality (ROD=18%). One 0.5" thick black SLATE bed noted. C7: Similar rock type to above, except close to very closely jointed (ROD=85%). Fractures typically <10 and 70-85 degrees from
Sample Information		Sample Description																					
Depth (ft)	Core Length (ft)	Strata Description	Sample Description																				
0 - 1.5	1.5	TOPSOIL	S1: Medium dense, dark brown, fine SAND and SILT, trace gravel, with roots and root fibers, moist.																				
1.5 - 4.5	3.0	Silty SAND (with Cobbles and Boulders)	S2: Refusal. Similar to S1, except fine to medium SAND, with organic litter.																				
4.5 - 52.2	47.7	BEDROCK (Quartzite)	C1: Very hard, light to dark gray, slightly weathered orange-red along fracture surfaces, closely jointed, poor quality QUARTZITE (ROD=38%). Fractures typically <15 and 45 degrees from horizontal. C2: Similar rock type to above (ROD=25%). C3: Similar rock type to above. C4: Similar rock type to above (ROD=25%). Fractures typically <10 and >70 degrees from horizontal. C5: Similar rock type to above, except close to very closely jointed (ROD=32%). Two 3/4" thick dark gray to black SLATE beds noted near bottom of run. C6: Similar rock type to above, except closely jointed, very poor quality (ROD=18%). One 0.5" thick black SLATE bed noted. C7: Similar rock type to above, except close to very closely jointed (ROD=85%). Fractures typically <10 and 70-85 degrees from																				
<p>Notes: 1) Ground surface elevation established in the field by Geodesign using a hand level. 2) Solid stem auger used on possible fine root cobbles, boulder at 5" depth. Large Quartzite boulders (18" to 24" diameter) observed approximately 1' below ground surface during solid stem auger advance. 3) L.D. casing set to 3.2' deep. Used 2.5" O.D. diameter roller bit to flush hole prior to coring. 4) Bedrock seen noted at 0.5' deep (C1/C2). Observed temporary change in water color to darker gray.</p>																							
<p>Scale: 1" = 10' Vertical, 1" = 10' Horizontal</p>																							
<p>Boring No.: B-5</p>																							

BORING LOG		Boring No.: B-5																					
Project Name		Page No.: 2 of 2																					
Route 125 Bridge RS 0174 (8) Middlebury, VT		File No.: 750-04.1																					
Checked By: JEL																							
<p><b>Geodesign Incorporated</b> Geotechnical Engineers/Environmental Consultants/Construction Engineers P.O. Box 688 Windsor, VT 05689 Phone: 802-474-8223/Fax: 802-474-5943</p> <p><b>H &amp; W Sells Engineering, Inc.</b> 1233 Shelburne Rd., Suite 300 St. Burlington, VT 05408 Phone: 802-652-5149</p>																							
<p>Boring Company: <b>H &amp; W Sells Engineering, Inc.</b> Personnel: <b>Myron Domingue</b> Contractor: <b>James Goodrich</b> Date Started: <b>July 8, 2003</b> Date Finished: <b>July 11, 2003</b> N. Coordinate: <b>532.7</b> E. Coordinate: <b>532.7</b> Ground Surface Elevation (feet): <b>532.7</b> Station: <b>14190.00</b> Offset: <b>27 ft LT</b></p>																							
<table border="1"> <thead> <tr> <th colspan="2">Sample Information</th> <th colspan="2">Sample Description</th> </tr> <tr> <th>Depth (ft)</th> <th>Core Length (ft)</th> <th>Strata Description</th> <th>Sample Description</th> </tr> </thead> <tbody> <tr> <td>0 - 1.5</td> <td>1.5</td> <td>TOPSOIL</td> <td>S1: Medium dense, dark brown, fine SAND and SILT, trace gravel, with roots and root fibers, moist.</td> </tr> <tr> <td>1.5 - 4.5</td> <td>3.0</td> <td>Silty SAND (with Cobbles and Boulders)</td> <td>S2: Refusal. Similar to S1, except fine to medium SAND, with organic litter.</td> </tr> <tr> <td>4.5 - 52.2</td> <td>47.7</td> <td>BEDROCK (Quartzite)</td> <td>C1: Very hard, light to dark gray, slightly weathered orange-red along fracture surfaces, closely jointed, poor quality QUARTZITE (ROD=38%). Fractures typically &lt;15 and 45 degrees from horizontal. C2: Similar rock type to above (ROD=25%). C3: Similar rock type to above. C4: Similar rock type to above (ROD=25%). Fractures typically &lt;10 and &gt;70 degrees from horizontal. C5: Similar rock type to above, except close to very closely jointed (ROD=32%). Two 3/4" thick dark gray to black SLATE beds noted near bottom of run. C6: Similar rock type to above, except closely jointed, very poor quality (ROD=18%). One 0.5" thick black SLATE bed noted. C7: Similar rock type to above, except close to very closely jointed (ROD=85%). Fractures typically &lt;10 and 70-85 degrees from</td> </tr> </tbody> </table>				Sample Information		Sample Description		Depth (ft)	Core Length (ft)	Strata Description	Sample Description	0 - 1.5	1.5	TOPSOIL	S1: Medium dense, dark brown, fine SAND and SILT, trace gravel, with roots and root fibers, moist.	1.5 - 4.5	3.0	Silty SAND (with Cobbles and Boulders)	S2: Refusal. Similar to S1, except fine to medium SAND, with organic litter.	4.5 - 52.2	47.7	BEDROCK (Quartzite)	C1: Very hard, light to dark gray, slightly weathered orange-red along fracture surfaces, closely jointed, poor quality QUARTZITE (ROD=38%). Fractures typically <15 and 45 degrees from horizontal. C2: Similar rock type to above (ROD=25%). C3: Similar rock type to above. C4: Similar rock type to above (ROD=25%). Fractures typically <10 and >70 degrees from horizontal. C5: Similar rock type to above, except close to very closely jointed (ROD=32%). Two 3/4" thick dark gray to black SLATE beds noted near bottom of run. C6: Similar rock type to above, except closely jointed, very poor quality (ROD=18%). One 0.5" thick black SLATE bed noted. C7: Similar rock type to above, except close to very closely jointed (ROD=85%). Fractures typically <10 and 70-85 degrees from
Sample Information		Sample Description																					
Depth (ft)	Core Length (ft)	Strata Description	Sample Description																				
0 - 1.5	1.5	TOPSOIL	S1: Medium dense, dark brown, fine SAND and SILT, trace gravel, with roots and root fibers, moist.																				
1.5 - 4.5	3.0	Silty SAND (with Cobbles and Boulders)	S2: Refusal. Similar to S1, except fine to medium SAND, with organic litter.																				
4.5 - 52.2	47.7	BEDROCK (Quartzite)	C1: Very hard, light to dark gray, slightly weathered orange-red along fracture surfaces, closely jointed, poor quality QUARTZITE (ROD=38%). Fractures typically <15 and 45 degrees from horizontal. C2: Similar rock type to above (ROD=25%). C3: Similar rock type to above. C4: Similar rock type to above (ROD=25%). Fractures typically <10 and >70 degrees from horizontal. C5: Similar rock type to above, except close to very closely jointed (ROD=32%). Two 3/4" thick dark gray to black SLATE beds noted near bottom of run. C6: Similar rock type to above, except closely jointed, very poor quality (ROD=18%). One 0.5" thick black SLATE bed noted. C7: Similar rock type to above, except close to very closely jointed (ROD=85%). Fractures typically <10 and 70-85 degrees from																				
<p>Notes: 1) Ground surface elevation established in the field by Geodesign using a hand level. 2) Solid stem auger used on possible fine root cobbles, boulder at 5" depth. Large Quartzite boulders (18" to 24" diameter) observed approximately 1' below ground surface during solid stem auger advance. 3) L.D. casing set to 3.2' deep. Used 2.5" O.D. diameter roller bit to flush hole prior to coring. 4) Bedrock seen noted at 0.5' deep (C1/C2). Observed temporary change in water color to darker gray.</p>																							
<p>Scale: 1" = 10' Vertical, 1" = 10' Horizontal</p>																							
<p>Boring No.: B-5</p>																							

PROJECT NAME: MIDDLEBURY  
PROJECT NUMBER: RS 0174(8)  
FILE NAME: z78f217borlog.dgn  
PROJECT LEADER: M.A. COLGAN  
DESIGNED BY: GEODESIGN  
BORING LOGS (5 OF 7)  
PLOT DATE: 8/27/2013  
DRAWN BY: B.J. MASSE  
CHECKED BY: G.S. GOODRICH  
SHEET 43 OF 104

