

Filled Out By: G. Demers

Date/Time: 10/28/10 1150

**Culvert Inspection Form**

Railroad: <u>WAGR CR1</u>	Town: <u>Trotford</u>
Valuation Sheet: <u>V 43</u> <u>18</u>	Valuation Stationing: +
Mile Post: <u>D 23.54</u>	GPS Coordinates: N: <u>43 51 28</u> W: <u>72 11 19</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

Height from Rail: N/A LOCATED UNDER ROAD TO CROSSING WEST SIDE

Length: \_\_\_\_\_ Height: 12" Width: 12" Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 140.46

Number of Photos Taken: 2

Remedial Action (if any):

NEEDS CLEANING

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



