

UPDATE

Filled Out By: G. DEMERS

Date/Time: 10/06/10 1035

**Culvert Inspection Form**

Railroad: <u>WACR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43</u> <u>90</u>	Valuation Stationing: <u>43A2 + 40.7</u>
Mile Post: <u>214.37</u>	GPS Coordinates: N: <u>44 44 43</u> W: <u>72 10 22</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

12" CONCRETE HEADER ON EAST SIDE (OUT)  
STEEL PWR DRAIN WEST SIDE (IN)

Height from Rail: 4'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



1923



1437

