

UPDATE

Filled Out By: G J DEMERS

Date/Time: 09/29/11

Culvert Inspection Form

Railroad: <u>WACK CRL</u>	Town: <u>BANTON</u>
Valuation Sheet: <u>V 43/90</u>	Valuation Stationing: <u>4729+01</u>
Mile Post: <u>L 14.63</u>	GPS Coordinates: N: <u>44 44.527</u> W: <u>72 10.145</u>

Type: Stone Box Culvert CMP C.I. Concrete ABS (Plastic) Other:
18"

Height from Rail: 4'

Length: _____ Height: _____ Width: _____ Depth: _____

Condition: Good Fair Poor

Culvert #: _____

Number of Photos Taken: 2

Remedial Action (if any):

OUTLET (EAST) NEEDS CLEANING

Additional Notes:



