

UPDATE

Filled Out By: G J DEMERS

Date/Time: 05/26/11

**Culvert Inspection Form**

Railroad: <u>WACK CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/90</u>	Valuation Stationing: <u>4710 + 72.0</u>
Mile Post: <u>L 14.98</u>	GPS Coordinates: N: <u>44 44.303</u> W: <u>72 09.940</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

24"

Height from Rail: 6'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any):

EAST RFD (OUTLET) 3/4 FULL

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

1498



