

Filled Out By: G J DEMERS

Date/Time: 07/21/11

Culvert Inspection Form

Railroad: <u>WACR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/89</u>	Valuation Stationing: <u>A650 + 49</u>
Mile Post: <u>L 16.11</u>	GPS Coordinates: N: <u>44 43.476</u> W: <u>72 09.189</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

3' X 3'

Height from Rail: 10' +

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 66 T

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

161



