

Filled Out By: RJ Demers

Date/Time: 07/26/11

**Culvert Inspection Form**

Railroad: <u>WARR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/88</u>	Valuation Stationing: <u>4613 + 02</u>
Mile Post: <u>L16.82</u>	GPS Coordinates: N: <u>44 43.004</u> W: <u>72 08.639</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

18"

Height from Rail: 4'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 66 J

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



68



