

1 UPDATE

Filled Out By: G J DEMERS

Date/Time: 07/26/11

Culvert Inspection Form

Railroad: <u>WACK CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/88</u>	Valuation Stationing: <u>4600 + 08</u>
Mile Post: <u>L17.07</u>	GPS Coordinates: N: <u>44 42.857</u> W: <u>72 08.429</u>

Type: ☒ Stone Box Culvert ☐ CMP ☐ C.I. ☐ Concrete ☐ ABS (Plastic) ☐ Other:

5' x 4' STONE CATTLE PASS

Height from Rail: 3'

Length: _____ Height: _____ Width: _____ Depth: _____

Condition: ☒ Good ☐ Fair ☐ Poor

Culvert #: 66E

Number of Photos Taken: 2

Remedial Action (if any):

Additional Notes:





