

UPDATE

Filled Out By: GJ DEMERS

Date/Time: 09/03/11

**Culvert Inspection Form**

Railroad: <u>WACR CR2</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/87</u>	Valuation Stationing: <u>4554 + 24.5</u>
Mile Post: <u>L 17.94</u>	GPS Coordinates: N: <u>44 42.489</u> W: <u>72 07.515</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

60" CATTLE PASS

Height from Rail: 6'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: BR # 64

Number of Photos Taken: 2

Remedial Action (if any):

---



---



---

Additional Notes:

---



---



---



---



