

UPDATE

Filled Out By: G J DEMERS

Date/Time: 08/03/11

**Culvert Inspection Form**

Railroad: <u>WACK CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/87</u>	Valuation Stationing: <u>A546 + 85.3</u>
Mile Post: <u>219.08</u>	GPS Coordinates: N: <u>44 42.439</u> W: <u>72 07.344</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:  
30"

Height from Rail: 8'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: BR # 63

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



