

Filled Out By: GJ DENNIS

Date/Time: 06/15/11

**Culvert Inspection Form**

Railroad: <u>WACR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/86</u>	Valuation Stationing: <u>4491 + 93.0</u>
Mile Post: <u>L 19.12</u>	GPS Coordinates: N: <u>44 42.113</u> W: <u>72 06.213</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

4' x 2.5'

Height from Rail: 4'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 61P

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



