

UPDATE

Filled Out By: GJ Demers

Date/Time: 06/06/11
1130

Culvert Inspection Form

| | |
|-------------------------|--|
| Railroad: WACR CR1 | Town: SUTTON |
| Valuation Sheet: V43/82 | Valuation Stationing: 4312 + 62 |
| Mile Post: 222.52 | GPS Coordinates: N: 44 40.929 W: 72 02.569 |

Type: Stone Box Culvert CMP C.I. Concrete ABS (Plastic) Other:

18"

Height from Rail: 4'

Length: _____ Height: _____ Width: _____ Depth: _____


Condition: Good Fair Poor

Culvert #: _____

Number of Photos Taken: 2

Remedial Action (if any):

Additional Notes:

A photograph of a tree trunk in a forest. A white identification tag is wrapped around the trunk, displaying the number '22.25'. The tree has a greyish-brown bark with some knots and a hole. A thin branch is leaning against the trunk. The background is filled with green foliage and other trees.

22.25



