

Filled Out By: G. Demers

Date/Time: 06/25/10

Culvert Inspection Form

Railroad: <u>WAGR CRL</u>	Town: <u>BURKE</u>
Valuation Sheet: <u>V 43</u> <u>77</u>	Valuation Stationing: <u>4039 + 04.4</u>
Mile Post: <u>L 27.69</u>	GPS Coordinates: N: <u>44 37 49</u> W: <u>71 58 19</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:  
30"

Height from Rail: 5'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 58D

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



