

UPDATE

Filled Out By: G. DEMERS

Date/Time: 11/12/10 1125

Culvert Inspection Form

Railroad: <u>WAGR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43</u> <u>96</u>	Valuation Stationing: <u>5043 + 83.8</u>
Mile Post: <u>28.68</u>	GPS Coordinates: N: <u>44 48 50</u> W: <u>72 12 17</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

18"

Height from Rail: 4'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 76 H

Number of Photos Taken: 2

Remedial Action (if any):

WEST END (INLET) FULL

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



