

UPDATE

Filled Out By: G. DEMERS

Date/Time: 11/12/10 1125

Culvert Inspection Form

Railroad: <u>WAGR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43</u> <u>96</u>	Valuation Stationing: <u>5043 + 83.8</u>
Mile Post: <u>28.68</u>	GPS Coordinates: N: <u>44 48 50</u> W: <u>72 12 17</u>

Type: Stone Box Culvert CMP C.I. Concrete ABS (Plastic) Other:

18"

Height from Rail: 4'

Length: _____ Height: _____ Width: _____ Depth: _____

Condition: Good Fair Poor

Culvert #: 76 H

Number of Photos Taken: 2

Remedial Action (if any):

WEST END (INLET) FULL

Additional Notes:

