

UPDATE

Filled Out By: G. DENNIS

Date/Time: 11/17/10 1200

**Culvert Inspection Form**

Railroad: <u>WACR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43</u> <u>95</u>	Valuation Stationing: <u>4979 + 44</u>
Mile Post: <u>L 9.88</u>	GPS Coordinates: N: <u>44 47 52</u> W: <u>72 12 37</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

24" PIPE

Height from Rail: 3'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 74 B

Number of Photos Taken: 2

Remedial Action (if any):

---



---



---

Additional Notes:

---



---



---



---

99

99



